

**Notices 34 -41**  
**March 2002**  
*Supplied Gratis*



# **SOUTH AFRICAN NOTICE TO MARINERS**

**MARCH 2002 EDITION**

**PUBLISHED MONTHLY  
BY THE  
HYDROGRAPHIC OFFICE  
CAPE TOWN**

## **CONTENTS**

- I Explanatory Notes and Index
- II SAN Notices to Mariners. Updates to Standard Navigational Charts
- III SAN Charts and SAN HO Publications - New Charts / Editions
- IV Corrections to SAN HO Publications
- V Corrections to SA List of Lights and Radio Services
- VI Reprints of Radio Navigational Warnings

## **IMPORTANT**

Mariners are requested to inform the Hydrographer, Private Bag X1, Tokai 7966, immediately of the discovery of new dangers, or changes or defects in aids to navigation and of shortcomings in South African charts or publications. Copies of form HO-16, which is a convenient form on which to send in a report, may be obtained gratis from any Official Chart Agent or the reproduction at the end of Section VI of the monthly edition of Notices to Mariners.

In addition to postal methods, the following additional communication facilities are available :

|                                   |   |
|-----------------------------------|---|
| Notices to Mariners Web site :    | Web : <a href="http://hydro.imt.za/hydronet/Ho/">http://hydro.imt.za/hydronet/Ho/</a>               |
| Urgent navigational information : | Fax : 021 787 2228<br>Phone : 021 787 2445  |
| Other navigational information :  | Phone : 021 787 2444<br>E-mail : <a href="mailto:hydrosan@iafrica.co.za">hydrosan@iafrica.co.za</a> |
| General information :             | Phone : 021 787 2408  |

**L.D. Reeder, Captain**  
**Hydrographer, SA Navy**  
**NAVAREA VII Co-ordinator**

## INDEX OF CHARTS AND PUBLICATIONS AFFECTED

---

| <b>SAN Charts</b> | <b>Notices</b> | <b>Pages</b> |
|-------------------|----------------|--------------|
| 55                | 35             | 1            |
| 58                | 36             | 1            |
| 78(INT 2660)      | 35             | 1            |
| 83(INT 7530)      | 37, 38         | 2            |
| 117               | 35             | 1            |
| 125               | 36, 37         | 1, 2         |
| 126               | 36, 37         | 1, 2         |
| 1001              | 34(T)          | 1            |
| 1024 (INT 7531)   | 36, 37, 38     | 1, 2         |
| 1025              | 36, 38         | 1, 2         |
| SC 9              | 36, 37         | 1, 2         |

| <b>SAN Publications</b>  | <b>Notices</b> | <b>Pages</b> |
|--|----------------|--------------|
| Annual Summary of South African Notices to Mariners 2002             | 39             | 4            |
| South African Sailing Directions Volume III SAN HO-23 (2001 Edition) | 40             | 4            |
| SA List of Lights and Radio Services - SAN HO-1                      | 41             | 4            |

---

### **Spheroid / GPS Positions**

All positions quoted in these Notices are referred to **Clarke 1880 (Mod) Spheroid** unless otherwise stated. On chart scales of **1: 100 000 and smaller**, positions from **GPS receivers** set to **WGS 84** may be plotted directly on these charts. Mariners are warned that **insertion of Clarke 1880 (or other) positions on Automatic Plotters which are set to WGS 84 Spheroid can result in inaccurate navigation practices.**

### **Temporary and Preliminary Notices**

These are indicated by (T) or (P) after the notice number. These are printed on one side of the paper in order that they may be cut and filed and are placed at the end of Section II. **Information from these notices is not included on charts before issue;** charts should be updated in pencil on receipt.

### **Permanent Notices**

Permanent corrections in Section II are marked by a star adjacent to the notice number to indicate that the notice is based on original information. Periodic lists of permanent corrections pertaining to affected navigational charts and publications are published annually and copies may be obtained from the Hydrographic Office or through a Chart Agent.

### **Chart Corrections**

Further details are contained in NP100 The Mariner's Handbook which should be consulted for the correct procedures of filing, inserting and noting all types of corrections on nautical charts and other hydrographic publications. The Handbook may be obtained from Admiralty Chart Agents in Cape Town and Durban. Consult SAN HO-6 for Symbols and Abbreviations used on SAN Charts and NP735 for an illustrated explanation of the IALA Maritime Buoyage System.

### **Provision of Notices to Mariners**

These Notices are *gratis* and may be obtained on request from the Hydrographic Office or through the approved Chart Agents. Additional copies required of "block" chart corrections can also be obtained through the above procedure.

### **Radio Navigational Warnings**

See Note at the start of Section III

## **GUIDANCE NOTES FOR VIEWING AND PRINTING NOTICES USING ADOBE ACROBAT**

For optimum results when viewing and printing material from the PDF digital files please note the following:

The minimum specification is a 486 PC with Windows 3.1 and 4MB of RAM.

When printing data from the files, ensure the Fit to Page icon in the Adobe Acrobat print menu is switched off before printing. Otherwise large text pages will be compressed, or large size Blocks may not fit the chart.

If printing text or monochrome NM Blocks, the minimum specification is an Inkjet or good quality Laser Postscript printer with at least 6 MB of memory. (NB. If using a Postscript printer, ensure the Postscript printer driver is installed).

For printing Colour NM Blocks the minimum specification of printer is a good quality Ink Jet/Laser printer with 300 dpi resolution or greater.

If using certain types of Ink Jet printer ensure the setting is set to Dithered screening not Pattern screening.

Printed colour copies should be compared with the colour image on screen to ensure that all the colours have reproduced correctly. Printer property resolution and ink density may need to be increased or adjusted to obtain the best results.

Ensure the Colour Ink Cartridge is in accordance with the printer manufacturers specifications. Minimum paper specification for printing Colour NM Blocks is International paper size A4, thickness/weight 80 gsm paper. (The same paper as used for NM Blocks in the NM Weekly). NB. (Ensure the paper quality is in accordance with the Printer manufacturers specifications).

**The Hydrographer does not accept any liability for the display and printing of these digital Notices to Mariners on the users equipment.**

I

**TEMPORARY NOTICES AND PRELIMINARY NOTICES**  
**In force 22 March 2002**

**TEMPORARY NOTICES**

**1999 Series**

|       |         |             |                               |
|-------|---------|-------------|-------------------------------|
| 74(T) | RSA     | East Coast  | Current Meter laid.           |
| 93(T) | Namibia | South Coast | Buoy and Current Meters laid. |

**2000 Series**

|       |         |             |                            |
|-------|---------|-------------|----------------------------|
| 59(T) | RSA     | South Coast | Current Meter - Buoy laid. |
| 75(T) | RSA     | South Coast | Current Meters laid.       |
| 88(T) | Namibia | South Coast | Current Meters laid.       |

**2001 Series**

|        |         |               |                                   |
|--------|---------|---------------|-----------------------------------|
| 82(T)  | Namibia | Walvis Bay    | Unlit vessel at anchor.           |
| 86(T)  | RSA     | St Helenabaai | Telemetry Marker Buoy laid.       |
| 94(T)  | Namibia | Lüderitz      | Bell Buoy unlit.                  |
| 95(T)  | Namibia | Lüderitz      | Tiger Reef Buoy missing.          |
| 102(T) | RSA     | SW Coast      | Arniston Light Character changed. |
| 107(T) | RSA     | Simon's Bay   | East Breakwater Light unlit.      |
| 109(T) | Namibia | Walvis Bay    | Wave Meter Buoys laid.            |

**2002 Series**

|       |         |            |                                    |
|-------|---------|------------|------------------------------------|
| 26(T) | Namibia | Lüderitz   | Diaz Point Fog Signal inoperative. |
| 27(T) | RSA     | False Bay  | Whittle Rock Buoy off station.     |
| 34(T) | Namibia | Walvis Bay | Waverider Buoy laid.               |

**PRELIMINARY NOTICES**

Nil prior to these Notices.

**2001 Series**

|        |     |                     |                          |
|--------|-----|---------------------|--------------------------|
| 61(P)  | RSA | South & East Coasts | Underwater cable laying. |
| 81(P)  | RSA | South & West Coasts | Underwater cable laying. |
| 113(P) | RSA | East Coast, Durban  | Vessel Traffic Services. |

II

**MISCELLANEOUS:**

1. Mariners are advised that South African Notices to Mariners is available in PDF format on the internet at

Website : <http://hydro.imt.za/hydronet/Ho/>.

2. Mariners attention is invited to the fact that the Hydrographic Office E-Mail number hydrosan@iafrica.co.za is only manned during office hours, Mondays to Friday, between the hours of 0600 UTC and 1400 UTC. Only matters of a routine nature must be forwarded by this method.

**\*34(T) NAMIBIA, South Coast -Walvis Bay - Waverider Buoy - Laid.**

1. Insert :  *Fl(5)20s* in position 25°53'.398 S 014°25'.512 E

2. Originally issued as Coastal Navigational Warning 105 of 2002.

*SAN Chart* 1001 (36/01)

*Source :* NAMPORT

(SAN 1001)

**\*35 SOUTH AFRICA, West Coast - Doringbaai Seaward - Non-dangerous Wreck**

1. Insert : *+++ PA* in position 31°54'.64 S 017°30'.77 E

2. Wreck is that of FV OCEANA SAPPHIRE, GRT 99, 22 metres sunk in depth of approximately 146m.

*SAN Charts :* 55 (39/01)

78(INT 2660) (73/01)

117 (47/01)

*Source :* SA Sea Products Ltd

(SAN 55, 78, 117)

**\*36 SOUTH AFRICA, South Coast - Port Elizabeth - Depth over Wreck.**

1. Amend : Least depth over wreck to read *10.4 m*

in position. 33°55'25".9 S 025°39'42".32 E  
WGS 84. Chart SAN 1024 (INT 7531) 33°55'16".9 S 025°39'42".3 E

2. Originally issued as Coastal Navigational Warning 103 of 2002.

*SAN Chart :* 58 (133/00)

125 (133/00)

126 (103/01)

1024 (INT 7531) (87/01)

1025 (55/01)

SC 9 (55/01)

*Source :* Hydrographer

(SAN 58, 125, 126, 1024, 1025, SC 9)

II (cont)

**\*37 SOUTH AFRICA, South Coast - Port Elizabeth - Obstruction.**

1. Delete : Symbol and legend  *Obstn*

in approximate position 33°54'16".0 S 025°42'02".0 E

*SAN Charts :* 83(INT 7530) (69/01)  
125 (36/02)  
126 (36/02)  
1024(INT 7531) (36/02)  
SC 9 (36/02)

*Source :* Hydrographer

(SAN 83, 125, 126, 1024, SC 9)

**\*38 SOUTH AFRICA, South Coast - Port Elizabeth - Vessel Traffic Services (VTS).**

1. Delete : "The VTS indicated on this chart is not yet in operation" from the Note on Vessel Traffic Services. (English and Afrikaans where applicable).

*SAN Charts :* 83(INT 7530) (37/02)  
1024(INT 7531) (37/02)  
1025 (36/02)

*Source :* Port Captain, Port Elizabeth

(SAN 83, 1024, 1025)

IIA

**LIST OF TEMPORARY AND PRELIMINARY NOTICES TO MARINERS ISSUED  
BY THE MOZAMBIQUE INSTITUTE OF HYDROGRAPHY AND NAVIGATION  
(INAHINA) IN FORCE**

**1998 Series**

|         |                 |                    |       |
|---------|-----------------|--------------------|-------|
| 2MOZ(T) | Port of Beira - | Lit Waverider Buoy | Laid. |
| 3MOZ(P) | Port of Beira - | White Spar Buoy    | Laid. |

**1999 Series**

|             |                     |        |          |
|-------------|---------------------|--------|----------|
| 12MOZ(P)/99 | Port of Quelimane - | Depths | Changed. |
|-------------|---------------------|--------|----------|

**2000 Series**

|             |               |                       |              |
|-------------|---------------|-----------------------|--------------|
| 10MOZ(T)/00 | South Coast - | Boa Paz Light (D6524) | Temp. unlit. |
|-------------|---------------|-----------------------|--------------|

**2001 Series**

|             |                  |  |                  |
|-------------|------------------|--|------------------|
| 01MOZ(T)/01 | Port of Maputo - | Buoy No. 2N                              | Temp. unlit.     |
| 03MOZ(T)/01 | Port of Beira -  | Buoy No. 10                              | Temp. unlit.     |
| 07MOZ(T)/01 | Port of Beira -  | Buoy No. T                               | Out of position. |
| 08MOZ(T)/01 | Port of Beira -  | Buoy No. 7                               | Repositioned.    |
| 15MOZ(T)/01 | North Coast      | Ilha Epidendron Light (D6582)            | Temp. unlit.     |
| 17MOZ(T)/01 | Porto de Maputo  | Beacon Esparcelado da<br>Catemby (D6508) | Temp. unlit      |

**2002 Series**

|             |                    |                          |                  |
|-------------|--------------------|--------------------------|------------------|
| 02MOZ(T)/02 | Porto de Quelimane | Buoy No P                | Temp. unlit.     |
| 03MOZ(T)/02 | Porto de Quelimane | Buoy No 1                | Out of position. |
| 04MOZ(P)/02 | Baía de Maputo     | Underwater Cable Laying. |                  |
| 05MOZ(P)/02 | Vilanculos         | Underwater Cable Laying. |                  |
| 06MOZ(P)/02 | Porto da Beira     | Underwater Cable Laying  |                  |

IIA

**07MOZ/02 MOZAMBIQUE, South Coast, Porto de Maputo - Buoyage.**

1. Reposition buoys to the following positions :

|         |                  |                   |         |                  |                   |
|---------|------------------|-------------------|---------|------------------|-------------------|
| Buoy 21 | 25°58'02".0557 S | 032°29'49".7997 E | Buoy 20 | 25°57'50".7416 s | 032°30'22".3660 E |
| Buoy 19 | 25°57'18".0500 S | 032°31'22".6120 E | Buoy 18 | 25°57'18".5639 S | 032°31'39".7177 E |
| Buoy 17 | 25°59'27".2254 S | 032°34'49".4443 E | Buoy 16 | 25°59'27".2254 S | 032°35'19".1985 E |

2. Originally issued as NAVAREA VII 033/02

Charts : MOZ 495 and BA 646  
Source : INAHINA (Notice MOZ 07/02)

### III

## **SAN CHARTS AND SAN HO PUBLICATIONS - NEW CHARTS / EDITIONS**

SOUTH AFRICAN SAILING DIRECTIONS Volume II SAN HO-22 is currently undergoing a major revision and upgrading. The new edition will be available mid-2002.

### IV

## **CORRECTIONS TO SAN PUBLICATIONS**

### **39 ANNUAL SUMMARY OF SOUTH AFRICAN NOTICES TO MARINERS - 2002**

1. Page 39 : APPENDIX C - PORT ELIZABETH AND APPROACHES

Amend : Note. to read : This VTS was established during July 2000 to ensure efficient entry and exit for vessels to the Port of Port Elizabeth.

### **40 SOUTH AFRICAN SAILING DIRECTIONS VOLUME III SAN HO-23 (2001 Edition)**

- Page 3-31 para 43. Amend 12.8 m to read 10.4 m

### V

### **41 CORRECTION TO SA LIST OF LIGHTS AND RADIO SERVICES - SAN HO-1 (New Edition 2001)**

1. Page 63 **Note:** Delete entire sentence.



VI

**NAVAREA VII and Coastal Navigational Warnings Bulletin  
in force as at 25 March 2002**

See NM 3/2002. Broadcast Warnings are available at Port Offices and remain valid until cancelled or until superseded by this and/or other broadcast bulletins.

**NAVAREA VII MESSAGES**

**Nil Prior to these Messages.**

**2002 Series**

019 S Atlantic, NE Sector, Angola Pride of Angola.  
033 Mozambique Channel, Porto de Maputo Buoys repositioned.

**COASTAL NAVIGATIONAL WARNINGS**

**Nil Prior to these Messages**

**2002 Series**

|     |               |              |  |
|-----|---------------|--------------|--|
| 014 | Namibia / RSA |              | Rig List.                                      |
| 069 | RSA           | East Coast   | Cooper Light DGPS inoperative.                 |
| 103 | RSA           | South Coast  | Port Elizabeth least depth over wreck altered. |
| 105 | Namibia       | Walvis Bay   | Waverider buoy deployed.                       |
| 123 | RSA           | West Coast   | Seismic Surveying by MV Western Trident.       |
| 129 | Namibia / RSA |              | Marine Mining Vessels.                         |
| 133 | RSA           | Est Coast    | Margate directional light pointing skywards.   |
| 135 | RSA           | West Coast   | Seismic Surveying by MV Geo Explorer.          |
| 138 | RSA           | South Coast  | Port Elizabeth Deal light unlit.               |
| 141 | RSA           | Agulhas Bank | Well testing and flaring ops.                  |
| 142 | RSA           | Table Bay    | Fairway buoy light unlit.                      |
| 144 | RSA           | East Coast   | Gunnery firing exercises Durban area.          |
| 145 | RSA           | South Coast  | Gunnery firing exercises.                      |

**ANNEX A**

USA Government Special Warning in force 18 December 2001

**SPECIAL WARNING NUMBER 120 WORLDWIDE**

1. Due to recent events in the Middle East and the American Homeland, U.S. Forces worldwide are operating at a heightened state of readiness and taking additional defensive precautions against terrorists and other potential threats. Consequently, all aircraft, surface vessels, and sub-surface vessels approaching U.S. Forces are requested to maintain radio contact with U.S. Forces on bridge-to-bridge channel 16, international air distress (121.5 Mhz VHF) or MILAIR distress (243.0 Mhz UHF).
2. U.S. Forces will exercise appropriate measures in self-defence if warranted by the circumstances. Aircraft, surface vessels, and sub-surface vessels approaching U.S. Forces will, by making prior contacts as described above, help make their intentions clear and avoid unnecessary initiation of such defensive measures.
3. U.S. Forces, especially when operating in confined waters, shall remain mindful of navigational considerations of aircraft, surface vessels, and sub-surface vessels in their immediate vicinity.
4. Nothing in the Special Warning is intended to impede or otherwise interfere with the freedom of navigation or overflight of any vessel or aircraft, or to limit or expand the inherent self-defence rights of U.S. Forces. This Special Warning is published solely to advise of the heightened state of readiness of U.S. Forces and to request that radio contact be maintained as described above. (Issued 16 Nov 2001)

**H0-16**

**Ship's Name :**

Consec No:

Date and Year:

## HYDROGRAPHIC NOTE

General Locality :

Subject :

Approx Position :                      Latitude:    Longitude:

SAN chart(s) affected :

Publications affected :

*(quote Volume, Supplement and Page)*

Full details :

A replacement copy of Chart No ..... is required.

Navigating Officer or Observer:

Captain or Master:

Ship (or address):

If Merchant Vessel add Line or                      :  
Company with Head Office address

*Note:*                      An acknowledgment of receipt will be sent and the information then used to the best advantage which may mean immediate action or inclusion in a revision in due course.

When a Notice to Mariners is issued the sender's ship or name is quoted as authority unless as sometimes happens the information is also received in a foreign Notice to Mariners.

### **Instructions for the forwarding information for South African charts and hydrographic publications**

1. Mariners are requested to notify the Hydrographer of the South African Navy, Private Bag X1, Tokai, 7966, or by Fax 021-787 2228, or e-mail *hydrosan@iafrica.co.za* when new or suspected dangers to navigation are discovered, changes observed in aids to navigation, or corrections to publications seem to be necessary.
2. Copies of this Form may be obtained gratis from the Hydrographer, Private Bag X1, Tokai, 7966 or the Chart Agents listed in Annual Summary of South African Notices to Mariners.
3. When a position is defined by sextant angles or bearing (true or magnetic north being specified) more than two should be used in order to provide a check. Any distances observed by radar should be quoted. When however there is a series of fixes along a ship's course, only the method of fixing and the objects used need to be indicated.
4. For positions obtained using GPS equipment the type of receiver and reference spheroid used must be included under Full Details.
5. A tracing from the largest scale chart or a cutting from it may be the best medium for forwarding details, and the alterations and additions should be shown thereon in red. A new copy of the chart will be sent if requested.
6. When soundings are forwarded the method used should be stated. If it is echo sounding, details should be forwarded as in Annual Notice to Mariners No 4. It is important to state whether echo depths are referred to the surface of the sea or to a transmitter at a specified depth below it. Time and date will be necessary to correct sounding for tidal height; and if any correction has already been made details must be given.
7. Reports which cannot be confirmed or are lacking in certain details should not be withheld. Shortcomings should be stressed and any firm expectation of being able to check the information on a succeeding voyage should be mentioned.
8. Reports of shoal soundings, navigation aids out of order, should be made by radio to the nearest coast radio station and addressed to HYDROSAN, CAPE TOWN. These reports should then be followed by documentary evidence on this form accompanied by the relevant echo sounder traces.