



SOUTH AFRICAN NOTICE TO MARINERS

MARCH 2003 EDITION

**PUBLISHED MONTHLY
BY THE
HYDROGRAPHIC OFFICE
CAPE TOWN**

CONTENTS

- I Explanatory Notes and Index
- II SAN Notices to Mariners. Updates to Standard Navigational Charts
- III SAN Charts and SAN HO Publications - New Charts / Editions
- IV Corrections to SAN HO Publications
- V Corrections to SA List of Lights and Radio Services
- VI Reprints of Radio Navigational Warnings

IMPORTANT

Mariners are requested to inform the Hydrographer, Private Bag X1, Tokai 7966, immediately of the discovery of new dangers, or changes or defects in aids to navigation and of shortcomings in South African charts or publications. Copies of form HO-16, which is a convenient form on which to send in a report, may be obtained gratis from any Official Chart Agent or the reproduction at the end of Section VI of the monthly edition of Notices to Mariners.

In addition to postal methods, the following additional communication facilities are available :

Notices to Mariners Web site : Web : <http://www.sanho.co.za>

Urgent navigational information : Fax : 021 787 2228
Phone : 021 787 2445

Other navigational information : Phone : 021 787 2444
E-mail : hydrosan@iafrica.co.za

General information : Phone : 021 787 2408

**L.D. Reeder, Captain
Hydrographer, SA Navy
NAVAREA VII Co-ordinator**

INDEX OF CHARTS AND PUBLICATIONS AFFECTED

SAN Charts	Notices	Pages
73(INT 2610)	38(T)	2
83(INT 7530)	36	1
125	36	1
1001(INT 2611)	38(T)	2
1030	37	1
1031(INT 7562)	37	1
SC 9	36	1

SAN Publications	Notices	Pages
South African Sailing Directions Volume III SAN HO-23 New Edition 2001	39/03	3

SAN Charts - New Charts / Editions	Notices	Pages
Nil		

Spheroid / GPS Positions

All positions quoted in these Notices are referred to **Clarke 1880 (Mod) Spheroid** unless otherwise stated. On chart scales of **1: 100 000 and smaller**, positions from **GPS receivers** set to **WGS 84** may be plotted directly on these charts. Mariners are warned that **insertion of Clarke 1880 (or other) positions on Automatic Plotters which are set to WGS 84 Spheroid can result in inaccurate navigation practices.**

Temporary and Preliminary Notices

These are indicated by (T) or (P) after the notice number. These are printed on one side of the paper in order that they may be cut and filed and are placed at the end of Section II. To assist in filing, the year is indicated after the notice number. **Information from these notices is not included on charts before issue;** charts should be updated in pencil on receipt.

Permanent Notices

Permanent corrections in Section II are marked by a star adjacent to the notice number to indicate that the notice is based on original information. Periodic lists of permanent corrections pertaining to affected navigational charts and publications are published annually and copies may be obtained from the Hydrographic Office or through a Chart Agent.

Chart Corrections

Further details are contained in NP100 The Mariner's Handbook which should be consulted for the correct procedures of filing, inserting and noting all types of corrections on nautical charts and other hydrographic publications. The Handbook may be obtained from Admiralty Chart Agents in Cape Town and Durban. Consult SAN HO-6 for Symbols and Abbreviations used on SAN Charts and NP735 for an illustrated explanation of the IALA Maritime Buoyage System.

Provision of Notices to Mariners

These Notices are *gratis* and may be obtained on request from the Hydrographic Office or through the approved Chart Agents. Additional copies required of "block" chart corrections can also be obtained through the above procedure.

Radio Navigational Warnings

See Note at the start of Section IV.

GUIDANCE NOTES FOR VIEWING AND PRINTING NOTICES USING ADOBE ACROBAT

For optimum results when viewing and printing material from the PDF digital files please note the following:

The minimum specification is a 486 PC with Windows 3.1 and 4MB of RAM.

When printing data from the files, ensure the Fit to Page icon in the Adobe Acrobat print menu is switched off before printing. Otherwise large text pages will be compressed, or large size Blocks may not fit the chart.

If printing text or monochrome NM Blocks, the minimum specification is an Inkjet or good quality Laser Postscript printer with at least 6 MB of memory. (NB. If using a Postscript printer, ensure the Postscript printer driver is installed).

For printing Colour NM Blocks the minimum specification of printer is a good quality Ink Jet/Laser printer with 300 dpi resolution or greater.

If using certain types of Ink Jet printer ensure the setting is set to Dithered screening not Pattern screening.

Printed colour copies should be compared with the colour image on screen to ensure that all the colours have reproduced correctly. Printer property resolution and ink density may need to be increased or adjusted to obtain the best results.

Ensure the Colour Ink Cartridge is in accordance with the printer manufacturers specifications. Minimum paper specification for printing Colour NM Blocks is International paper size A4, thickness/weight 80 gsm paper. (The same paper as used for NM Blocks in the NM Weekly). NB. (Ensure the paper quality is in accordance with the Printer manufacturers specifications).

The Hydrographer does not accept any liability for the display and printing of these digital Notices to Mariners on the users equipment.

I

TEMPORARY NOTICES AND PRELIMINARY NOTICES
In force 25 March 2003

TEMPORARY NOTICES

2001 Series

82(T)	Namibia	Walvis Bay	Unlit vessel at anchor.
95(T)	Namibia	Lüderitz	Tiger Reef Buoy missing.

2002 Series

71(T)	Namibia	Lüderitz seawards	Foul Area.
78(T)	Namibia	Baker's Bay	Foul Area.
89(T)	Namibia	Bogenfels	Anchor Obstructions, Foul Area.
99(T)	RSA	South Sand Bluff	Light unlit.
111(T)	RSA	Saldanha Bay	Oil Production Platform in position.

2003 Series

38(T)	Namibia	Walvis Bay	Spit Bell Buoy missing.
-------	---------	------------	-------------------------

PRELIMINARY NOTICES

Nil prior to these Notices.

2002 Series

98(P)	RSA	Agulhas Bank	Proposed Sable Oil Field.
-------	-----	--------------	---------------------------

II

SA NAVY SAN CHARTS OF SOUTH AFRICAN AND NAMIBIA THAT ARE REFERRED TO THE WGS84 SPHEROID

The following is the current list of SAN charts of South Africa and Namibia that are referred to the WGS84 spheroid.

76(INT 2640)	79(INT 2670)	87(INT 7570)	113
125	132	133	1001(INT 2611)
1003	1012(INT 2672)	1015	1017
1024(INT 7531)	1025(INT 7532)	1032(INT 7572)	1033(INT 7571)
2004	SC3	SC5	

ERRATUM

1. Amend South African Notice to Mariners 86/02, **Submarine Cables**, as follows:-

Chart SAN 55

Delete : All positions referring to the submarine cable and replace with the following :

a. 33°42'.60 S	018°26'.15 E	b. 33°45'.76 S	018°13'.56 E	c. 33°46'.53 S	018°10'.97 E
d. 33°46'.19 S	018°06'.24 E	e. 33°46'.19 S	018°06'.23 E	f. 33°46'.47 S	018°04'.26 E
g. 33°48'.25 S	017°59'.97 E	h. 33°50'.56 S	017°59'.16 E	i. 33°52'.60 S	017°55'.97 E
j. 33°53'.02 S	017°45'.32 E	k. 33°54'.61 S	017°43'.69 E	l. 33°55'.63 S	017°38'.01 E
m. 33°57'.00 S	017°33'.66 E				

As well as :

a. 33°42'.48 S	018°25'.92 E	b. 33°42'.47 S	018°25'.02 E	c. 33°42'.68 S	018°22'.49 E
d. 33°50'.21 S	017°41'.60 E	e. 33°50'.91 S	017°21'.04 E	f. 33°53'.35 S	017°16'.05 E
g. 33°51'.79 S	016°45'.18 E				

Chart SAN 56

Delete : All positions referring to the submarine cable and replace with the following :

a. 33°42'.48 S	018°25'.92 E	b. 33°45'.76 S	018°13'.56 E	c. 33°46'.53 S	018°11'.00 E
d. 33°46'.19 S	018°06'.24 E	e. 33°46'.19 S	018°06'.23 E	f. 33°46'.47 S	018°04'.26 E
g. 33°48'.25 S	017°59'.97 E	h. 33°50'.56 S	017°59'.16 E	i. 33°52'.60 S	017°55'.97 E
j. 33°53'.02 S	017°45'.32 E	k. 33°54'.61 S	017°43'.69 E	l. 33°55'.63 S	017°38'.03 E
m. 33°58'.98 S	017°26'.43 E	n. 34°01'.50 S	017°15'.00 E	o. 34°07'.92 S	017°04'.77 E
p. 34°41'.66 S	016°32'.91 E	q. 35°07'.18 S	016°28'.77 E	r. 35°07'.48 S	016°28'.72 E
s. 35°15'.81 S	016°33'.03 E	t. 35°31'.40 S	016°41'.83 E	u. 35°43'.40 S	016°52'.02 E
v. 35°46'.49 S	016°54'.77 E	w. 36°06'.14 S	017°11'.49 E		

As well as :

a. 33° 42'.48 S	018° 25'.92 E	b. 33° 42'.68 S	018° 22'.49 E	c. 33° 50'.21 S	017° 41'.60 E
d. 33° 50'.91 S	017° 21'.04 E	e. 33° 53'.35 S	017° 16'.05 E	f. 33° 51'.79 S	016° 45'.18 E
g. 33° 46'.14 S	016° 30'.00 E	h. 32°49'.00 S	015°24'.67 E		

2. Amend South African Notice to Mariners 105/02, **Submarine Cables**, as follows:-

Under **Chart SAN SC 4** amend the last position of the cable, in the second section, to read

o. 33°53'.02 S 017°51'.78 E

MISCELLANEOUS

1. Mariners are advised that South African Notices to Mariners is available in PDF format on the internet at

Website : <http://www.sanho.co.za>

2. Mariners attention is invited to the fact that the Hydrographic Office E-Mail address hydrosan@iafrica.co.za is only manned during office hours, Mondays to Friday (Public Holidays excluded), between the hours of 0600 UTC and 1400 UTC. Only matters of a routine nature must be forwarded by this method. All urgent messages must be forwarded via Fax number 021 787 2228.

II

***36 SOUTH AFRICA, South Coast - St Francis Bay - Wreck**

1. Insert : +++ PA in position 34°03'.00 S 025°10'00 E

2. Wreck is that of F/V André C

SAN Charts : 83(INT 7530) (105/02)
 125 (110/02)
 SC 9 (43/02)

Source : SAMSA

(SAN 83, 125)

***37 SOUTH AFRICA, East Coast - Durban and Approaches - Millennium Tower and Radar Tower**

Chart SAN 1030

Approaches to Durban

- | | | | | |
|-------------|--------------------------|-------------------------|----------------|-----------------|
| 1. Insert : | ⚓ SS(INT)(146)
(R Lt) | in position | 29°52'31".56 S | 031°03'28".13 E |
| 2. Insert : | ⦿ Radar SC (93)
RW | in position | 29°52'22".71 S | 031°03'37".13 E |
| 3. Delete : | ⦿ Sig Tr
(conspic) | in approximate position | 29°52'31".00 S | 031°03'29".20 E |

Chart SAN 1031(INT 7562)

Durban Harbour

- | | | | | |
|-------------|--------------------------|-------------------------|----------------|-----------------|
| 4. Insert : | ⚓ SS(INT)(146)
(R Lt) | in position | 29°52'31".56 S | 031°03'28".13 E |
| 5. Insert : | ⦿ Radar SC (93)
RW | in position | 29°52'22".71 S | 031°03'37".13 E |
| 6. Delete : | ⦿ SS (INT)(99) | in approximate position | 29°52'31".40 S | 031°03'28"50 E |

SAN Charts : 1030 (30/03)
 1031(INT 7562) (30/03)

Source : National Ports Authority

(SAN 1030, 1031)

II

38(T)/03 NAMIBIA, Walvis Bay Approaches - Spit Bell Buoy

1. Insert : *Missing* adjacent to Bell Buoy in position 22°51'.63 S 014°26'.86 E

2. Originally issued as Coastal Navigation Warning 062/2003

SAN Charts : 73(INT 2610) (45/01)
 1001(INT 2611) (93/02)

Source : Namibian Ports Authority

(SAN 73, 1001)

III

SAN CHARTS AND SAN HO PUBLICATIONS - NEW CHARTS / EDITIONS

SOUTH AFRICAN SAILING DIRECTIONS Volume 2 SAN HO-22 and Volume 3 SAN HO-23 are, unfortunately, out of print. New editions are currently undergoing major revision and upgrading with the intention of eventually making them available on the website. It is anticipated that the new editions will be available during the early part of 2003. South African Maritime Safety Authority (SAMSA) has been informed of the present situation regarding these publications.

IV

CORRECTION TO SAN PUBLICATIONS

39/03 SOUTH AFRICAN SAILING DIRECTIONS VOLUME III - SAN HO-23 New edition 2001

1. Page 3-22 :

Insert new page 3-22 (see run-on)

2. Page 6-36

Insert new paragraphs after paragraph 47 :

VESSEL TRAFFIC SERVICES (VTS)

47a. This section provides general information and direction for vessels proceeding in the Approach Waters to Durban Harbour.

47b. Cross reference should be made to the relevant chapters and charts issued by the Hydrographer SA Navy.

47c. For more detail information on the individual VESSEL TRAFFIC SERVICES see *Annual Summary of South African Notices to Mariners No 18*, *South African List of Lights and Radio Signals (SA HO-1)* and the *Mariners Handbook (NP100)*.

3. Page 7-27 line 1 :

Amend : *African Notice to Mariners No 19* to read *No 18*.

2. Bladsy 6-36

Voegby nuwe paragrawe na paragraaf 47 :

VAARTUIG VERKEERSDIENSTE (VVD)

47a. Hierdie seksie verskaf algemene informasie en rigting vir vaartuie wat in die toegangswaters na Durbanhawe vaar.

47b. Kruisverwysing moet na dietoepaslike hoofstukke en seekaarte wat deur die Hidrograaf SA Vloot uitgeryk word, gemaak word.

47c. Vir meer besonderhede met betrekking tot die VAARTUIG VERKEERSDIENSTE verwys na die *Jaarlikse Opsomming van Suid-Afrikaanse Kennisgewings aan Seevaarders No 18*, *Suid-Afrikaanse Liglys en Radiodienste (SAN HO-1)* en die "Mariners Handbook" (NP100)

3. Bladsy 7-27 ry 2 :

Wysig : *aan Seevaarders nr 19* om te lees *nr 18*.

V

**CORRECTION TO SA LIST OF LIGHTS AND RADIO SERVICES - SAN HO-1
(New Edition 2002)**

Nil

VI

**NAVAREA VII and Coastal Navigational Warnings Bulletin
in force as at 25 March 2003**

See NM 3/2003. Broadcast Warnings are available at Port Offices and remain valid until cancelled or until superseded by this and/or other broadcast bulletins.

NAVAREA VII MESSAGES

Nil Prior to these Messages.

2003Series

031	Angola		Rig List.
034	Mozambique	Ponta Matirre	Light unlit.
035	Mozambique	Baia de Maputo	Buoys repositioned.
036	Mozambique	Ponta Saide Ali	Light unlit.
037	Mozambique	Ilha Tambuzi	Light unlit.
041	Mozambique	Vilhena	Light unlit.
042	S. Atlantic and Indian Oceans		US Special Warning No 121.
044	S. Atlantic S. Eastern Sector		Containers lost overboard.

COASTAL NAVIGATIONAL WARNINGS

Nil Prior to these Messages

2003Series

062	Namibia	Walvis Bay	Spit Bell Buoy missing.
087	RSA	Simon's Bay	Missile Shaped Target moored.
105	RSA	Cape Recife	D.G.P.S. unreliable.
107	RSA	Cape Agulhas area	Missile firings.
110	Namibia	Bogenfels	Swamped mining tools abandoned.
123	RSA/Namibia		Marine Mining Vessels.
124	Namibia	South Coast	Anchor spread abandoned.
125	RSA	Hout Bay	North Mole decayed.
126	RSA	Groenriviermond	Light unlit.
128	RSA	False Bay	Pyrotechnics firing.
129	RSA	False Bay	Gunnery firing.
130	RSA	Saldanha Bay	Magnetometers laid.

VI

ANNEX A

USA Government Special Warning in force 18 December 2001

SPECIAL WARNING NUMBER 120 WORLDWIDE

1. Due to recent events in the Middle East and the American Homeland, U.S. Forces worldwide are operating at a heightened state of readiness and taking additional defensive precautions against terrorists and other potential threats. Consequently, all aircraft, surface vessels, and sub-surface vessels approaching U.S. Forces are requested to maintain radio contact with U.S. Forces on bridge-to-bridge channel 16, international air distress (121.5 Mhz VHF) or MILAIR distress (243.0 Mhz UHF).
2. U.S. Forces will exercise appropriate measures in self-defence if warranted by the circumstances. Aircraft, surface vessels, and sub-surface vessels approaching U.S. Forces will, by making prior contacts as described above, help make their intentions clear and avoid unnecessary initiation of such defensive measures.
3. U.S. Forces, especially when operating in confined waters, shall remain mindful of navigational considerations of aircraft, surface vessels, and sub-surface vessels in their immediate vicinity.
4. Nothing in the Special Warning is intended to impede or otherwise interfere with the freedom of navigation or overflight of any vessel or aircraft, or to limit or expand the inherent self-defence rights of U.S. Forces. This Special Warning is published solely to advise of the heightened state of readiness of U.S. Forces and to request that radio contact be maintained as described above. (Issued 16 Nov 2001)

USA Government Special Warning in force 20 March 2003

SPECIAL WARNING NUMBER 121. PERSIAN GULF

1. Coalition Naval Forces may conduct military operations in the Eastern Mediterranean Sea, Red Sea, Gulf of Aden, Arabian Sea, Gulf of Oman and Arabian Gulf. The timely and accurate identification of all vessels and aircraft in these areas are critical to avoid the inadvertent use of force.
2. All vessels are advised that coalition Naval Forces are prepared to exercise appropriate measures in self-defence to ensure their safety in the event they are approached by vessels or aircraft. Coalition Forces are prepared to respond decisively to any hostile acts or indications of hostile intent. All maritime vessels or activities that are determined to be threats to Coalition Naval Forces will be subject to defensive measures, including boarding, seizure, disabling or destruction, without regard to registry or location. Consequently, surface vessels, sub-surface vessels and all aircraft approaching Coalition Naval Forces are advised to maintain radio contact on Bridge-to-Bridge channel 16, International Air Distress (121.5 MHZ VHF) or Military Air Distress (243.0 MHZ UHF)
3. Vessels operating in the Middle East, Eastern Mediterranean Sea, Red Sea, Gulf of Oman, Arabian Sea and Arabian Gulf are subject to query, being stopped, boarded and searched by US/Coalition warships operating in support of operations against Iraq. Vessels found to be carrying contraband bound for Iraq or carrying and/or laying Naval mines are subject to detention, seizure and destruction. This notice is effective immediately and will remain in effect until further notice.

HO-16 (July 2002)

HYDROGRAPHIC NOTE

(for instructions, see overleaf)

Date

Ref. No

Name of ship or sender :

Address of sender :

.....

.....

Tel/Fax/Telex No. e-mail address of sender (if appropriate) :

General locality Subject :

Position : Lat :

Long :

SAN Chart(s) affected :

Edition dated :

Position fixing system used :

Datum set :

Latest Monthly Edition of Notice to Mariners held :

Publications affected : (Edition No date of latest supplement, page and Light List No. etc.)

Details:

A replacement copy of Chart(s) No(s) is required, but see 4 overleaf.

Signature of observer/reporter :

HYDROGRAPHIC NOTE

Forwarding information for South African Charts and Hydrographic Publications

INSTRUCTIONS

1. Mariners are requested to notify the Hydrographer of the South African Navy, Private Bag X1, Tokai, 7966, or by Facimile 021 7872228 or E-mail *hydrosan@iafrica.co.za* when new or suspected dangers to navigation are discovered, changes observed in aids to navigation, or corrections to publications seen to be necessary. The *Mariner's Handbook (NP 100) Chapter 8* gives general instructions. The provisions of international and national laws should be complied with when forwarding such reports.
2. This form and its instructions have been designed to help both the sender and the recipient. It should be used, or followed closely, whenever appropriate. Copies of this Form may be obtained gratis from the SAN Hydrographic Office at the above address or principal Chart Agents (see *Annual Notice to Mariners No.1*).
3. When a **position** is defined by sextant angles or bearings (true or magnetic being specified) more than two should be used in order to provide a check. Distances observed by radar and the readings of Loran, Decca, etc., should be quoted. Latitude and longitude should only be used specifically to position the details when they have been fixed by astronomical observations or GPS and a full description of the method, equipment and datum (where applicable) used should be given.
4. A cutting from the largest scale chart is the best medium for forwarding details, the alterations and additions being shown thereon in red. When requested, a new copy will be sent in replacement of a chart that has been used to forward information, or when extensive observations have involved defacement of the observer's chart. If it is preferred to show the amendments on a tracing of the largest scale chart (rather than on the chart itself) these should be in red as above, but adequate details from the chart must be traced in black ink to enable the amendments to be fitted correctly.
5. When **soundings** are obtained *The Mariner's Handbook (NP 100)* should be consulted. The echo sounding trace should be marked with times, depths, etc., and forwarded with the report. It is important to state whether the echo sounder is set to register depths below the surface or below the keel; in the latter case the vessel's draught should be given. Time and date should be given in order that corrections for the height of the tide may be made where necessary. The make, name and type of set should also be given.
6. Modern **echo sounders** frequently record signals from echoes received back after one or more rotations of the stylus have been completed. Thus with a set whose maximum range is 500m, an echo recorded at 50m may be from depths of 50m, 550m or even 1050m. Soundings recorded beyond the set's nominal range can usually be recognised by the following:
 - (a) the trace being weaker than normal for the depth recorded,
 - (b) the trace passing through the transmission line,
 - (c) the feathery nature of the trace.

As a check that apparently shoal soundings are not due to echoes received beyond the set's nominal range, soundings should be continued until reasonable agreement with charted soundings is reached. However, soundings received after one or more rotations of the stylus can still be useful and should be submitted if they show significant differences from charted depths.

7. Reports which cannot be confirmed or are lacking in certain details should not be withheld. Shortcomings should be stressed and any firm expectation of being able to check the information on a succeeding voyage should be mentioned.
8. Reports of **shoal soundings**, uncharted dangers and navigational aids out of order should, at the mariner's discretion, also be made by radio to the nearest coast radio station. The draught of modern tankers is such that any uncharted depth under 30 metres or 15 fathoms may be of sufficient importance to justify a radio message.

Note : An acknowledgement or receipt will be sent and the information then used to the best advantage which may mean immediate action or inclusion in a revision in due course. When a Notice to Mariners is issued, the sender's ship or name is quoted as authority unless (as sometimes happens) the information is also received from other authorities. An explanation of the use made of contributions from all parts of the world would be too great a task and a further communication should only be expected when the information is of outstanding value or has unusual features.

before altering towards the harbour entrance or port or anchorage.

DIRECTION FOR THE EASTERN APPROACH TO PORT ELIZABETH

72.. **Ships approaching Port Elizabeth from the eastward** should keep to the **north of Riy Bank** running in on a course of **270°** with the **Deal Light** ((*Fl. 10s28m24M*)) right ahead. This will give a clearance of 4 miles to the north of Riy Bank and a course into the correct approach lane of the **Vessel Traffic Services (VTS)** (see below).

73. **Ships leaving Port Elizabeth towards the eastward** during fine weather, are recommended to **proceed through Bird Island Passage** (see section 3.5.83). By so doing they will avoid the full force of the Agulhas Current and possibly experience the **favourable Counter Current**.

VESSEL TRAFFIC SERVICES (VTS)

74. This section provides general information and directions for vessels proceeding in the Approach Waters to Port Elizabeth Harbour.

75. Cross reference should be made to the relevant chapters and charts issued by the Hydrographer SA Navy.

76. For more detail information on the individual VESSEL TRAFFIC SERVICES see *Annual Summary of South African Notices to Mariners No18, South African List of Lights and Radio Signals (SAN HO-1)* and the *Mariners Handbook (NP100)*.

ligboei te vaar voordat daar na die hawe ingang of hawe ankerplek verander word.

RIGLYNE VIR DIE OOSTELIKE TOEGANG TOT PORT ELIZABETH.

72. **Skepe wat Port Elizabeth van die ooste nader** moet **noord van Riy-bank** hou en op 'n koers van **270°** met **Deal-lig** (*Fl. 10s28m24M*) regvoor invaar. Hierdie sal 'n vry ruimte van 4 myl noord van Riy-bank toelaat en 'n koers na die toepaslike naderbaan van die **Vaartuig Verkeersdienste (VVD)** gee (kyk onder).

73. **Skepe wat Port Elizabeth na die ooste verlaat** gedurende goeieweer word aanbeveel om deur **Bird-eiland deurvaart te vaar** (sien seksie 3.5.83). Sodoende sal hulle die volle krag van die Agulhasstroom verhoed en moontlik die **gunstige teenstroom** ondervind.

VAARTUIG VERKEERSDIENSTE (VVD)

74. Hierdie seksie verskaf algemene informasie en rigting vir vaartuie wat in die toegangswaters na Port Elizabeth-hawe vaar.

75. Kruisverwysing moet na die toepaslike hoofstukke en seekarte wat deur die Hidrograaf SA Vloot uitgeryk word, gemaak word.

76. Vir meer besonderhede met betrekking tot die VAARTUIG VERKEERSDIENSTE verwys na die *Jaarlikse Opsomming van Suid-Afrikaanse Kennisgewings aan Seevaarders No 18, Suid-Afrikaanse Liglys en Radiodienste (SAN HO-1)* en die *Mariners Handbook (NP100)*.