



**Notice 27-42
January 2007
Supplied Gratis**

SOUTH AFRICAN NOTICE TO MARINERS

January 2007 EDITION

**PUBLISHED MONTHLY
BY THE
HYDROGRAPHIC OFFICE
CAPE TOWN**

CONTENTS

- I Explanatory Notes and Index
- II SAN Notices to Mariners. Updates to Standard Navigational Charts
- III SAN Charts and SAN HO Publications - New Charts / Editions
- IV Corrections to SAN HO Publications
- V Corrections to SA List of Lights and Radio Services
- VI Reprints of Radio Navigational Warnings

IMPORTANT

Mariners are requested to inform the Hydrographer, Private Bag X1, Tokai 7966, immediately of the discovery of new dangers, or changes or defects in aids to navigation and of shortcomings in South African charts or publications. Copies of form HO-16, which is a convenient form on which to send in a report, may be obtained gratis from any Official Chart Agent or the reproduction at the end of Section VI of the monthly edition of Notices to Mariners.

In addition to postal methods, the following additional communication facilities are available :

Notices to Mariners Web site :	Web : http://www.sanho.co.za
Urgent navigational information :	Telex : 95 527946 (ANS BACK: NAVY SA) Fax : +27 21 787 2228 Phone : +27 21 787 2445
Other navigational information :	Fax : +27 21 787 2233 Phone : +27 21 787 2444 E-mail : hydrosan@iafrica.com
General information :	Phone : +27 21 787 2408

**Captain A. Kampfer
Hydrographer, SA Navy
NAVAREA VII Co-ordinator**

INDEX OF CHARTS AND PUBLICATIONS AFFECTED

SAN Charts	Notices	Pages
55	31(T)	2
75 (INT 2630)	27(T), 28(T), 29(T), 30(T)	1, 2
79 (INT 2670)	33	2
118	33	2
1010	32	2
1011	32	2
1012 (INT 2672)	32	2
1016	34	3
1017	34, 35	3
1024 (INT 7531)	37	3
1033 (INT 7571)	39	4
SC 2	32	2
SC 4	33	2
SC 5	36(T), 38	3, 4

SAN Publications	Notices	Pages
SA Sailing Directions Vol II (SAN HO-22) - 2002 4th Edition	40	6
SA Sailing Directions Vol III (SAN HO-23) - 2003 4th Edition	41	6
SA List of Lights and Radio Signals (HO-1) - 2005 New Edition	42	7

SAN Charts - New Charts / Editions	Notices	Pages
Nil		

SAN Charts and Publications - Permanently Withdrawn	Notices	Pages
Nil		

SANHO Publications - New / New Editions	Notices	Pages
Nil		

Spheroid / GPS Positions

All positions quoted in these Notices are referred to **Clarke 1880 (Mod) Spheroid** unless otherwise stated. On chart scales of **1: 100 000 and smaller**, positions from **GPS receivers** set to **WGS 84** may be plotted directly on these charts. Mariners are warned that **insertion of Clarke 1880 (or other) positions on Automatic Plotters which are set to WGS 84 Spheroid can result in inaccurate navigation practices.**

Temporary and Preliminary Notices

These are indicated by (T) or (P) after the notice number. These are printed on one side of the paper in order that they may be cut and filed and are placed at the end of Section II. To assist in filing, the year is indicated after the notice number. **Information from these notices is not included on charts before issue**; charts should be updated in pencil on receipt.

Permanent Notices

Permanent corrections in Section II are marked by a star adjacent to the notice number to indicate that the notice is based on original information. Periodic lists of permanent corrections pertaining to affected navigational charts and publications are published annually and copies may be obtained from the Hydrographic Office or through a Chart Agent.

Chart Corrections

Further details are contained in NP100 The Mariner's Handbook which should be consulted for the correct procedures of filing, inserting and noting all types of corrections on nautical charts and other hydrographic publications. The Handbook may be obtained from Admiralty Chart Agents in Cape Town and Durban. Consult SAN HO-6 for Symbols and Abbreviations used on SAN Charts and NP735 for an illustrated explanation of the IALA Maritime Buoyage System.

Provision of Notices to Mariners

These Notices are *gratis* and may be obtained on request from the Hydrographic Office or through the approved Chart Agents. Additional copies required of "block" chart corrections can also be obtained through the above procedure.

Radio Navigational Warnings

See Note at the start of Section VI.

GUIDANCE NOTES FOR VIEWING AND PRINTING NOTICES USING ADOBE ACROBAT

For optimum results when viewing and printing material from the PDF digital files please note the following:

The minimum specification is a 486 PC with Windows 3.1 and 4MB of RAM.

When printing data from the files, ensure the Fit to Page icon in the Adobe Acrobat print menu is switched off before printing. Otherwise large text pages will be compressed, or large size Blocks may not fit the chart.

If printing text or monochrome NM Blocks, the minimum specification is an Inkjet or good quality Laser Postscript printer with at least 6 MB of memory. (NB. If using a Postscript printer, ensure the Postscript printer driver is installed).

For printing Colour NM Blocks the minimum specification of printer is a good quality Ink Jet/Laser printer with 300 dpi resolution or greater.

If using certain types of Ink Jet printer ensure the setting is set to Dithered screening not Pattern screening.

Printed colour copies should be compared with the colour image on screen to ensure that all the colours have reproduced correctly. Printer property resolution and ink density may need to be increased or adjusted to obtain the best results.

Ensure the Colour Ink Cartridge is in accordance with the printer manufacturers specifications. Minimum paper specification for printing Colour NM Blocks is International paper size A4, thickness/weight 80 gsm paper. (The same paper as used for NM Blocks in the NM Weekly). NB. (Ensure the paper quality is in accordance with the Printer manufacturers specifications).

The Hydrographer does not accept any liability for the display and printing of these digital Notices to Mariners on the users equipment.

TEMPORARY NOTICES AND PRELIMINARY NOTICES
In force 30 January 2007

CANCELLED NOTICES

Nil

TEMPORARY NOTICES

2002 Series

78(T)	Namibia	Baker's Bay	Foul Area.
89(T)	Namibia	Bogenfels	Anchor Obstructions, Foul Area.

2003 Series

64(T)	RSA	Durban Oil Terminal SBM	Buoy laid.
-------	-----	-------------------------	------------

2004 Series

Nil

2005 Series

42(T)	RSA	Elandsbaai	Scientific buoy deployed.
-------	-----	------------	---------------------------

2006 Series

33(T)	RSA	Tugela Lighthouse	Temporary light and structure.
40(T)	RSA	Mossel Bay	Temporary buoys deployed.
65(T)	RSA	Richards Bay Harbour	Pelican Island West Groyne North End light and East Groyne light unlit.
68(T)	RSA	Hondeklip Bay	Temporary light and structure.
69(T)	RSA	Gordon's Bay	Silting in Harbour.
75(T)	RSA	False Bay	Whittle Rock Buoy light unlit.
77(T)	RSA	Cape Recife	Lighthouse DGPS unmonitored.
81(T)	RSA	Richards Bay	Buoy No 30 in new position.
82(T)	RSA	Richards Bay	LM2 front light unlit.
89(T)	RSA	Richards Bay	Light at SW end of Berth 305 out of commission.
96(T)	RSA	Table Bay	Submarine cable.
121(T)	RSA	East London	Redeployment of Oceanographic Environmental Moorings.

2007 Series

27(T)	Namibia	Boat Bay	Floating rope sighted.
28(T)	Namibia	Lüderitz	M/V Sakawe Miner lost anchor with wire attached.
29(T)	Namibia	Lüderitz	Floating ropes without markers.
30(T)	Namibia	Bogenfels	Swamped mining tools and floating ropes.
31(T)	RSA	St Helena Bay	R/V Africana deployed sub-sea buoy.
36(T)	RSA	Arniston	Quick flashing red light temporarily unlit.

PRELIMINARY NOTICES

2005 Series

Nil

2006 Series

120(P)	RSA	Agulhas Bank	New gas pipeline established.
--------	-----	--------------	-------------------------------

2007 Series

Nil

II

ERRATUM

Nil

SA NAVY SAN CHARTS OF SOUTH AFRICA AND NAMIBIA THAT ARE REFERRED TO THE WGS 84 SPHEROID

27 (INT 204)	76 (INT 2640)	79 (INT 2670)	84 (INT 7540)
87 (INT 7570)	90 (INT 2051)	1001 (INT 2611)	1002 (INT 2631)
1012 (INT 2672)	1013 (INT 2681)	1020 (INT 7521)	1024 (INT 7531)
1025 (INT 7532)	1027 (INT 7541)	1030 (INT 7561)	1032 (INT 7572)
1033 (INT 7571)	2004 (INT 9056)		
1	113	114	115
125	126	132	133
134	1003	1015	1017
SC3	SC5		

MISCELLANEOUS

1. Mariners are advised that the primary and most reliable means of communication with HYDROSAN for all messages is via Telex : 95 527946 (ANS BACK : NAVY SA) or alternatively via Facsimile number : +27 21 787 2228.

2. Current and archived South African Notices to Mariners is available in PDF format on the internet at Website : <http://www.sanho.co.za>

27(T)/07 NAMIBIA, Boat Bay - Floating rope

Source : Hydrographer (Previously issued as CNW 277 of 2006)

SAN 75 (INT 2630) [Previous Update - 71/05]

1. Floating rope has been sighted in approximate position 26° 26'.6 S 014° 57'.4 E

(SAN 75)

28(T)/07 NAMIBIA, Lüderitz - Lost anchor

Source : Hydrographer (Previously issued as CNW 305 of 2006)

SAN 75 (INT 2630) [Previous Update - 71/05]

1. M/V Sakawe Miner lost an anchor with its wire attached in approximate position 26° 51'.3 S 015° 05'.1 E

(SAN 75)

29(T)/07 NAMIBIA, Lüderitz Bay - Floating ropes

Source : Hydrographer (Previously issued as CNW 411 of 2006)

SAN 75 (INT 2630) [Previous Update - 71/05]

1. Floating ropes without unlit marker buoys reported between approximate positions (a) 26° 51'.8 S 015° 04'.5 E
(b) 26° 51'.6 S 015° 04'.5 E

(SAN 75)

II cont/...

30(T)/07 NAMIBIA, Bogenfels - Swamped mining tools

Source : Hydrographer (Previously issued as CNW 410 of 2006)

SAN 75 (INT 2630) [Previous Update - 71/05]

1. Swamped minings tools with ropes attached in approximate position 27° 30'.4 S 015° 24'.4 E

(SAN 75)

31(T)/07 SOUTH AFRICA, South West Coast, West of St Helena Bay - Sub-sea buoy deployed

Source : Hydrographer (Previously issued as CNW 348 of 2006)

SAN 55 [Previous Update - 86/06]

1. R/V Africana deployed a sub-sea buoy in approximate position 32° 40'.0 S 016° 48'.5 E

(SAN 55)

32* SOUTH AFRICA, South West Coast, Saldanha Bay - Discontinuation of Racons

Source : NPA Lighthouse Services

SAN 1012 (INT 2672) [Previous Update - 106/06]

SAN 1011 [Previous Update - 106/06]

SAN 1010 [Previous Update - 100/05]

SAN SC 2 [Previous Update - 107/06]

1. Delete : Racon symbols and legends in approximate position
a) 33° 02'.7 S 017° 58'.2 E
b) 33° 02'.8 S 018° 03'.2 E

(SAN 1012, 1011, 1010, SC 2)



33* SOUTH AFRICA, West Coast, Dassen Island - Discontinuation of Target Buoy

Source : Hydrographer

SAN 118 [Previous Update - 118/06]

SAN 79 (INT 2670) [Previous Update - 86/06]

SAN SC 4 [Previous Update - 118/06]

1. Delete :  Target and  Target in approximate position 33° 35'.0 S 018° 08'.5 E

(SAN 118, 79, SC 4)




II cont/...

34* SOUTH AFRICA, South West Coast, False Bay - Aids to navigation

Source : Naval Harbour Master

SAN 1017 [Previous Update - 108/06]


SAN 1016 [Previous Update - 97/06]

1. Amend:  and  in approximate position 34° 12'.5 S 018° 27'.7 E
to read  (SAN 1017, 1016)

35* SOUTH AFRICA, South West Coast, False Bay - Beacon

Source : Naval Harbour Master

SAN 1017 [Previous Update - 34/07]

1. Delete :  in approximate position 34° 12'.1 S 018° 27'.4 E
(SAN 1017)

36(T)/07 SOUTH AFRICA, South West Coast, Arniston - Light unlit

Source : NPA Lighthouse Services (Previously issued as **CNW 639 of 2006**)

SAN SC 5 [Previous Update - 108/06]

1. Quick flashing red light unlit in approximate position 34° 40'.0 S 020° 13'.9 E
(SAN SC 5)

37* SOUTH AFRICA, South Coast, Approaches to Port Elizabeth - Discontinuation of light

Source : NPA Lighthouse Services

SAN 1024 (INT 7531) [Previous Update - 79/06]

1. Delete :  Fl.R.3s13m5M in approximate position 33° 58'.8 S 025° 39'.6 E
(SAN 1024)

II cont/...

38* SOUTH WEST COAST - FALSE BAY TO CAPE AGULHAS

Source : Hydrographer

SAN SC 5 [Previous Update - 108/07]

SMALL CRAFT SAILING DIRECTIONS - CAPE AGULHAS TO RYSPUNT





1. Insert accompanying block correction to replace para 6.

(SAN SC 5)

39* SOUTH AFRICA, East Coast, Richards Bay Harbour - Lights and aids to navigation

Source : NPA Lighthouse Services

SAN 1033 (INT 7571) [Previous Update - 99/06]

- | | | | | |
|------------------|--|--|------------------|-------------------|
| 1. Amend: |  Q.R. | in position | 28° 47' 24".88 S | 032° 01' 20".74 E |
| to read |  FI.R.2s
LM 11 | | | |
| 2. Amend: |  F.G. | in position | 28° 47' 23".26 S | 032° 01' 17".51 E |
| to read |  F.G.
LM 12 | | | |
| 3. Insert: | ----- | bearing 119°30'/299°30' direction (TN) for a distance of 11 cables from the rear leading light LM 12. | | |
| 4. Insert legend | 299°30' parallel to transit line | in approximate position | 28° 47' 51" S | 032° 02' 14" E |
| 5. Insert: | ----- | Leading beacons LM 9 and LM 10. Transit bearing 020°/200° direction (TN), solid line for a distance of 4,5 cables from the main channel leading line, thence a pecked line to the rear leading beacon LM 10. | | |
| 6. Insert legend | 020° parallel to leading line | in approximate position | 28° 48' 23" S | 032° 05' 22" E |

(SAN 1033)

IIA

LIST OF TEMPORARY AND PRELIMINARY NOTICES TO MARINERS ISSUED BY THE MOZAMBIQUE INSTITUTE OF HYDROGRAPHY AND NAVIGATION (INAHINA) IN FORCE

Important Notice : Mariners are advised that positions for Mozambique Notices are given in WGS 84 Datum. Caution is therefore advised when plotting positions on large scale British Admiralty charts that are not of the same datum.

Nil prior to these Notices.

2003 Series

MOZ 07/03 (T)	Porto de Maputo	Buoys out of position.
---------------	-----------------	------------------------

2005 Series

MOZ 04/05 (T)	Port of Quelimane	Buoy 3 temporarily out of position.
MOZ 05/05 (T)	Port of Maputo	Cias de Bombagem temporarily unlit.
MOZ 06/05 (T)	Port of Quelimane	Buoy 2 temporarily out of position.
MOZ 13/05 (T)	Port of Quelimane	Buoy A temporarily unlit.
MOZ 14/05 (T)	Port of Quelimane	Buoy 4A temporarily out of position.
MOZ 15/05 (T)	Port of Quelimane	Buoy 2A temporarily out of position.
MOZ 17/05 (T)	Port of Quelimane	Spar Buoy 12 out of position.
MOZ 26/05 (T)	Port of Angoche	Mafamede Lighthouse characteristics.

2006 Series

MOZ 02/06 (T)	Port of Quelimane	Buoy 9 out of position.
MOZ 05/06 (T)	Port of Quelimane	Buoy 2A out of position.
MOZ 11/06 (T)	Port of Inhambane	Buoy A out of position.
MOZ 12/06 (T)	Port of Inhambane	Buoy 9 out of position.
MOZ 13/06 (T)	Port of Beira	Buoy A out of position.
MOZ 14/06 (T)	Port of Quelimane	Buoy A out of position.
MOZ 15/06 (T)	Chonguene Quay	Anchored platform.
MOZ 21/06 (T)	Port of Angoche	Changes of the channel buoys and numbers.

2007 Series

Nil

MOZ 21/06(T) MOZAMBIQUE, Port of Angoche - Changes made to channel buoys and numbers

Source : INAHINA

MOZ 16309 and BA 2933

1. Make the following changes to the channel buoys and numbers:

Buoy	Kind	Colour	Position	Characteristics
P	-----	Red	16° 13' 56".5 S 040° 03' 14".5 E	MO (A) W8s
1	Spar buoy	Green	16° 13' 18".0 S 040° 02' 44".2 E	
2	Spar buoy	Red	16° 13' 43".3 S 040° 02' 55".0 E	
3	Spar buoy	Green	16° 15' 01".4 S 039° 54' 03".9 E	
4	Spar buoy	Red	16° 13' 12".1 S 040° 02' 24".3 E	
6	Spar buoy	Red	16° 14' 04".7 S 040° 01' 23".8 E	
8	Spar buoy	Red	16° 14' 52".7 S 040° 00' 26".4 E	
10	Spar buoy	Red	16° 15' 19".0 S 039° 58' 35".2 E	
W	Spar buoy	Red	16° 14' 07".5 S 039° 53' 50".2 E	

III

NEW CHARTS AND SAN HO PUBLICATIONS - NEW CHARTS/EDITIONS

Nil

IV

CORRECTION TO SAN HO PUBLICATIONS

40/07 SOUTH AFRICAN SAILING DIRECTIONS VOL II (SAN HO-22) 4th EDITION - 2002

Source : Hydrographer

1. Page 4-21 para 17 **MARCUS ISLAND**

Delete : "A **Racon (Morse "M")** is co-located with the light."

2. Page 4-22 para 27 **ENTRANCE CHANNEL**

Delete : "The **tower** from which the rear of these lights is exhibited is fitted with a **Racon (Morse "C")**."

Source : Naval Harbour Master

3. Page 5-7 para 7 **YZERFONTEINPUNT TO BLOUBERGSTRAND**

Delete : "An *unlit yellow Target buoy*, fitted with a radar reflector, is moored in a position 8.5 miles westward of Bokpunt."

4. Page 6-15 para 26 **CAPE POINT TO ROMAN ROCKS**

Amend : "... in **white and red horizontal bands**."

to read: "**white**."

41/07 SOUTH AFRICAN SAILING DIRECTIONS VOL III (SAN HO-23) 4th EDITION - 2002

1. Page 7-15 para 40 **RICHARDS BAY HARBOUR**

Insert : After ... 80 m apart: "Leading beacons situated on the Northern side of East Bay, LM 9 and LM 10 on transit bearing 020°/200°(T). Indicates the entrance to the dredger basin."

2. Page 7-16 para 49 **RICHARDS BAY HARBOUR**

Insert : New sub-paragraph: "Lights in line, LM 11 and LM 12 is situated west of the General Cargo Quay, which marks a 50 m clearance off the buoy line, buoys no's 22 - 28."

V

**42/07 CORRECTION TO SA LIST OF LIGHTS AND RADIO SIGNALS - SAN HO-1
2005 New Edition**

Source : NPA Lighthouse Services

1. Page 14 **LIGHTS AND FOG SIGNALS - SOUTH AFRICA - SALDANHA BAY**

Delete : The following entries in column 8 : **Racon (C)** and **Racon (M)**

2. Page 21 **LIGHTS AND FOG SIGNALS - SOUTH AFRICA - ALGOA BAY**

Delete : The following entry in toto :

(Z6108 (D6401)	Shark Rock Pier	33 58.8 25 39.6	Fl.R.3s	13	5	White Pole	f/0.4
-------------------	-----------------	--------------------	---------	----	---	------------	-------

3. Page 25 **RICHARDS BAY HARBOUR**

Mhlatuze

Insert : Under Name (Col 2)

Lights in line 299°30'

Z6400
(D6483.32)

Z6400.1
(D6483.321)

Amend : Under Characteristic (Col 4)

Z6400 (D6483.32)	O.R.	to read	Fl.R.2s
---------------------	------	---------	---------

4. Page 27, 28 **RACON LISTING - SOUTH AFRICA**

Delete : The following entries in toto :

7386	Saldanha Bay (Marcus Island) (Z5690)	360°	12 n miles	33°02'.73 S	17°58'.17 E
	72 s (3cm) M				
7387	Saldanha Bay (Lynch Point) (Z5687.1)	360°	12 n miles	33°02'.77 S	18°03'.15 E
	72 s (3 cm) C				

5. Page 29 **DIAGRAM - LOCATION OF RACONS**

Delete : Racon numbers 7386 and 7387, and symbol from diagram.

VI

NAVAREA VII and Coastal Navigational Warnings Bulletin in force as at 30 January 2007

See NM 3/2006. Broadcast Warnings are available at Port Offices and remain valid until cancelled or until superseded by this and/or other broadcast bulletins.

NAVAREA VII MESSAGES

Nil Prior to these Messages

2006 Series

086	S Atlantic Ocean	Angola	Riglist.
158	Mozambique	Port of Angoche	Changes to buoys and numbering.

2007 Series

005	S Indian Ocean	SW Sector	Tug Atlantic Hickory towing Boabarge 7 to Malaysia.
-----	----------------	-----------	---

COASTAL NAVWARNING MESSAGES

Nil Prior to these Messages

2006 Series

277	Namibia	Boat Bay	Floating rope sighted.
305	Namibia	Lüderitz	M/V Sakawe Miner lost anchor.
348	RSA	St Helena Bay	RV Africana deployed sub-sea buoy.
353	RSA	Cape Barracouta	Rig Modu Pride left well heads.
410	Namibia	Bogenfels	Swamped Mining Tools.
411	Namibia	Lüderitz	Floating Ropes.
489	RSA	Mossel Bay	Rig Pride South Seas left equipment.
491	RSA	Gordons Bay	Two orange buoys anchored.
590	RSA	Cape Barracouta	Rig Pride South Seas new position.
619	RSA	Mossel Bay	Rig Pride South Seas left equipment.
639	RSA	Arniston	Red light unlit.
687	Namibia	Lüderitz	M/V Namakwa new anchor spread.
694	RSA	Table Bay	Tug rig Deliverer and tow at anchor.
695	RSA	Elands Bay	Special marker buoy unlit.

2007 Series

005	RSA	Richards Bay	Unmarked wreck.
014	RSA	Knysna	Current meters deployed.
023	RSA	False Bay	Whittle Rock Buoy not in position.
032	RSA	Cape Agulhas to Cape Barracouta	Gunnery exercise.
033	Namibia	Lüderitz	Buoy sighted.
038	RSA	Cape Point	Tug Salvicount towing operation.
039	Namibia	Lüderitz	Sakawe Miner new anchor spread.
040	Namibia	Lüderitz	M/V Kovambo anchor spread.
041	RSA	False Bay	Gunnery exercise.
042	RSA	Melkbos Punt to Kaap Hangklip	Gunnery exercise.
043	Namibia	Lüderitz	M/V D.F. Discoverer anchor spread.
044	RSA	Cape Barracouta	Rig Pride South Seas Flaring ops.
045	RSA	False Bay	Gunnery exercise.

VI
ANNEX A

USA Government Special Warning in force 24 August 2003

SPECIAL WARNING NUMBER 120 WORLDWIDE

1. Due to recent events in the Middle East and the American Homeland, U.S. Forces worldwide are operating at a heightened state of readiness and taking additional defensive precautions against terrorists and other potential threats. Consequently, all aircraft, surface vessels, and sub-surface vessels approaching U.S. Forces are requested to maintain radio contact with U.S. Forces on bridge-to-bridge channel 16, international air distress (121.5 Mhz VHF) or MILAIR distress (243.0 Mhz UHF).
2. U.S. Forces will exercise appropriate measures in self-defence if warranted by the circumstances. Aircraft, surface vessels, and sub-surface vessels approaching U.S. Forces will, by making prior contacts as described above, help make their intentions clear and avoid unnecessary initiation of such defensive measures.
3. U.S. Forces, especially when operating in confined waters, shall remain mindful of navigational considerations of aircraft, surface vessels, and sub-surface vessels in their immediate vicinity.
4. Nothing in the Special Warning is intended to impede or otherwise interfere with the freedom of navigation or overflight of any vessel or aircraft, or to limit or expand the inherent self-defence rights of U.S. Forces. This Special Warning is published solely to advise of the heightened state of readiness of U.S. Forces and to request that radio contact be maintained as described above. (Issued 16 Nov 2001).

USA Government Special Warning in force 24 August 2003

SPECIAL WARNING NUMBER 121 PERSIAN GULF

1. Coalition Naval Forces may conduct military operations in the Eastern Mediterranean Sea, Red Sea, Gulf of Aden, Arabian Sea, Gulf of Oman and Arabian Gulf. The timely and accurate identification of all vessels and aircraft in these areas are, critical to avoid the inadvertent use of force.
2. All vessels are advised that coalition Naval Forces are prepared to exercise appropriate measures in self-defense to ensure their safety in the event they are approached by vessels or aircraft. Coalition Forces are prepared to respond decisively to any hostile acts or indications of hostile intent. All maritime vessels or activities that are determined to be threats to Coalition Naval Forces will be subject to defensive measures, including boarding, seizure, disabling or destruction, without regard to registry or location. Consequently, surface vessels, sub-surface vessels and all aircraft approaching Coalition Naval Forces are advised to maintain radio contact on Bridge-to-Bridge channel 16, International Air Distress (121.5 MHZ VHF) or Military Air Distress (243.0 MHZ UHF).
3. Vessels operating in the Middle East, Eastern Mediterranean Sea, Red Sea, Gulf of Oman, Arabian Sea and Arabian Gulf are subject to query, being stopped, boarded and searched by US/Coalition warships operating in support of operations against Iraq. Vessels found to be carrying contraband bound for Iraq or carrying and/or laying Naval mines are subject to detention, seizure and destruction. This notice is effective immediately and will remain in effect until further notice.

VI cont/...

USA Government Special Warning in force 12 May 2005

SPECIAL WARNING NUMBER 122 EAST AFRICA

1. The US Government has received unconfirmed information that terrorists may attempt to mount a maritime attack using speedboats against a western ship - possibly in East Africa. No additional information is available on the planning, timing or intended targets of the maritime attack. This notice is effective immediately and will remain in effect until further notice.

USA Government Special Warning in force 11 November 2005

SPECIAL WARNING NUMBER 123 EAST AFRICA

1. Due to continuing conditions of armed conflict and lawlessness in Somalia and waters off its coast, mariners are advised to avoid the port of Muqdisho (Mogadishu) and to remain at least 200 nautical miles distant from the Somali coast. The US government does not have an embassy in Somalia and cannot provide services to US citizens.

2. Recent vessel hijackings off the east coast of Somalia demonstrate that pirates are able to conduct at sea hijackings from as far south as Kismaayo (Chisimayu) (00-22S), though vessels are advised to transit no closer than 02-00S, to as far north as Eyl (08-00N), and out to a distance of 170 miles. The first known attempt to hijack a cruise vessel occurred in November 2005. All merchant vessels transiting the coast of Somalia, no matter how far offshore, should increase anti-piracy precautions and maintain a heightened state of vigilance. Pirates are reported to have used previously hijacked ships as bases for further attacks.

3. Another reported pirate tactic has been to issue a false distress call to lure a ship close inshore. Therefore, caution should be taken when responding to distress calls keeping in mind it may be a tactic to lure a vessel into a trap.

4. Victimized vessels have reported two to three (2-3) speedboats measuring six to nine meters (6-9M) in length. Each vessel has a crew of three to six (3-6) armed men with AK-47s and shoulder launched rockets, which are opening fire on vessels in broad daylight in order to intimidate them into stopping.

5. To date, vessels that increase speed and take evasive maneuvers avoid boarding while those that slow down are boarded, taken to the Somali coastline, and released after successful ransom payment, often after protracted negotiations of as much as 11 weeks.

HO-16 (August 2002)

HYDROGRAPHIC NOTE
(for instructions, see overleaf)

Date

Ref. No

Name of ship or sender :

Address of sender :

.....

.....

Tel/Fax/Telex No. e-mail address of sender (if appropriate) :

General locality Subject :

Position : Lat : Long :

SAN Chart(s) affected : Edition dated :

Position fixing system used : Datum set :

Latest Monthly Edition of Notice to Mariners held :

Publications affected : (Edition No date of latest supplement, page and Light List No. etc.)

Details:

A replacement copy of Chart(s) No(s) is required, but see 4 overleaf.

Signature of observer/reporter :

HYDROGRAPHIC NOTE

Forwarding Information for South African Charts and Hydrographic Publications

INSTRUCTIONS

1. Mariners are requested to notify the Hydrographer of the South African Navy, Private Bag X1, Tokai, 7966, or by Facimile 021 7872228 or E-mail *hydrosan@iafrica.com* when new or suspected dangers to navigation are discovered, changes observed in aids to navigation, or corrections to publications seen to be necessary. The *Mariner's Handbook (NP 100) Chapter 8* gives general instructions. The provisions of international and national laws should be complied with when forwarding such reports.

2. This form and its instructions have been designed to help both the sender and the recipient. It should be used, or followed closely, whenever appropriate. Copies of this Form may be obtained gratis from the SAN Hydrographic Office at the above address or principal Chart Agents (see *Annual Notice to Mariners No.1*).

3. When a **position** is defined by sextant angles or bearings (true or magnetic being specified) more than two should be used in order to provide a check. Distances observed by radar and the readings of Loran, Decca, etc., should be quoted. Latitude and longitude should only be used specifically to position the details when they have been fixed by astronomical observations or GPS and a full description of the method, equipment and datum (where applicable) used should be given.

4. A cutting from the largest scale chart is the best medium for forwarding details, the alterations and additions being shown thereon in red. When requested, a new copy will be sent in replacement of a chart that has been used to forward information, or when extensive observations have involved defacement of the observer's chart. If it is preferred to show the amendments on a tracing of the largest scale chart (rather than on the chart itself) these should be in red as above, but adequate details from the chart must be traced in black ink to enable the amendments to be fitted correctly.

5. When **soundings** are obtained *The Mariner's Handbook (NP 100)* should be consulted. The echo sounding trace should be marked with times, depths, etc., and forwarded with the report. It is important to state whether the echo sounder is set to register depths below the surface or below the keel; in the latter case the vessel's draught should be given. Time and date should be given in order that corrections for the height of the tide may be made where necessary. The make, name and type of set should also be given.

6. Modern **echo sounders** frequently record signals from echoes received back after one or more rotations of the stylus have been completed. Thus with a set whose maximum range is 500m, an echo recorded at 50m may be from depths of 50m, 550m or even 1050m. Soundings recorded beyond the set's nominal range can usually be recognised by the following:

- (a) the trace being weaker than normal for the depth recorded,
- (b) the trace passing through the transmission line,
- (c) the feathery nature of the trace.

As a check that apparently shoal soundings are not due to echoes received beyond the set's nominal range, soundings should be continued until reasonable agreement with charted soundings is reached. However, soundings received after one or more rotations of the stylus can still be useful and should be submitted if they show significant differences from charted depths.

7. Reports which cannot be confirmed or are lacking in certain details should not be withheld. Shortcomings should be stressed and any firm expectation of being able to check the information on a succeeding voyage should be mentioned.

8. Reports of **shoal soundings**, uncharted dangers and navigational aids out of order should, at the mariner's discretion, also be made by radio to the nearest coast radio station. The draught of modern tankers is such that any uncharted depth under 30 metres or 15 fathoms may be of sufficient importance to justify a radio message.

9. **Port information** should be forwarded on Form HO-16a together with Form HO-16. Form HO-16a lists the information required for South African Sailing Directions and should be used as an *aide memoire*. Where there is insufficient space on the form an additional sheet should be used.

Note : An acknowledgement or receipt will be sent and the information then used to the best advantage which may mean immediate action or inclusion in a revision in due course. When a Notice to Mariners is issued, the sender's ship or name is quoted as authority unless (as sometimes happens) the information is also received from other authorities. An explanation of the use made of contributions from all parts of the world would be too great a task and a further communication should only be expected when the information is of outstanding value or has unusual features.

HO-16a (May 2004)

**HYDROGRAPHIC NOTE FOR PORT
INFORMATION**

(To accompany Form HO-16)

Name of ship or sender :

Address of sender :

Ref. No.

.....

Date :

.....

1. NAME OF PORT	
2. GENERAL REMARKS Principal activities and trade. Latest population figures and date. Number of ships or tonnage handled per year. Maximum size of vessel handled. Copy of Port Handbook if available.	
3. ANCHORAGES Designation, depths, holding ground, shelter afforded.	
4. PILOTAGE Authority for requests. Embarkation position. Regulations.	
5. DIRECTIONS Entry and berthing information. Tidal Streams. Navigational aids.	
6. TUGS Number available and max. hp.	
7. WHARVES Names, numbers or positions. Lengths. Depths alongside. Heights above Chart Datum. Facilities available.	
8. CARGO HOLDING Containers, lighters, Ro-Ro etc.	
9. CRANES Brief details and max. capacity.	

<p>10. REPAIRS</p> <p>Hull, machinery and underwater. Ship and boat yards. Docking or slipping facilities. Give size of vessels handled or dimensions. Hards or ramps. Divers.</p>	
<p>11. RESCUE AND DISTRESS</p> <p>Salvage, lifeboat, NSRI, etc.</p>	
<p>12. SUPPLIES</p> <p>Fuel with type and quantities available. Fresh water with rate of supply. Provisions.</p>	
<p>13. SERVICES</p> <p>Medical. De-ratting. Consuls. Ship chandlery, compass adjustment, tank cleaning, hull painting.</p>	
<p>14. COMMUNICATIONS</p> <p>Road, rail and air services available. Nearest airport or airfield. Port radio and information service with frequencies and hours of operating.</p>	
<p>15. PORT AUTHORITY</p> <p>Designation, address and telephone number.</p>	
<p>16. SMALL CRAFT FACILITIES</p> <p>Information and facilities for small craft (eg yachts) visiting the port. Yacht Clubs, berths, etc.</p>	
<p>17. VIEWS</p> <p>Photographs (where permitted) of the approaches, leading marks, the entrance to the harbour etc. Picture postcards may also be useful.</p>	

Signature of observer/reporter

.....

To accompany Notice to Mariners no. 38 of 2007.

The approach to the concrete **launching ramp** at **Waenhuiskrans** (Arniston) is marked by a **quick flashing red light**. The red light is used by local fishermen as a marker to indicate the large rock as a navigational hazard when negotiating the slipway. Entry by vessels without local knowledge is not recommended. The ramp has a motorised winch.

The approach to the concrete **launching ramp** at **Waenhuiskrans** (Arniston) is marked by a **quick flashing red light**. The red light is used by local fishermen as a marker to indicate the large rock as a navigational hazard when negotiating the slipway. Entry by vessels without local knowledge is not recommended. The ramp has a motorised winch.