



**Notice 102-111
November 2008
Supplied Gratis**

SOUTH AFRICAN NOTICE TO MARINERS

November 2008 EDITION

**PUBLISHED MONTHLY
BY THE
HYDROGRAPHIC OFFICE
CAPE TOWN**

CONTENTS

- I Explanatory Notes and Index
- II SAN Notices to Mariners. Updates to Standard Navigational Charts
- III SAN Charts and SAN HO Publications - New Charts / Editions
- IV Corrections to SAN HO Publications
- V Corrections to SA List of Lights and Radio Services
- VI Reprints of Radio Navigational Warnings

IMPORTANT

Mariners are requested to inform the Hydrographer, Private Bag X1, Tokai 7966, immediately of the discovery of new dangers, or changes or defects in aids to navigation and of shortcomings in South African charts or publications. Copies of form HO-16, which is a convenient form on which to send in a report, may be obtained gratis from any Official Chart Agent or the reproduction at the end of Section VI of the monthly edition of Notices to Mariners.

In addition to postal methods, the following additional communication facilities are available :

Notices to Mariners Web site :	Web : http://www.sanho.co.za
Urgent navigational information : (24 Hour Service)	Telex : 95 527946 (ANS BACK: NAVY SA) Fax : +27 21 787 2228
Other navigational information : (0730 - 1600 Mon - Fri)	Fax : +27 21 787 2233 Phone : +27 21 787 2445/2444 E-mail : hydrosan@iafrica.com
General information : (0730 - 1600 Mon - Fri)	Phone : +27 21 787 2408

**Captain A. Kampfer
Hydrographer, SA Navy
NAVAREA VII Co-ordinator**

INDEX OF CHARTS AND PUBLICATIONS AFFECTED

SAN Charts	Notices	Pages
54	103	2
56	104	3
57	106	3
73 (INT 2610)	102(T)	2
80 (INT 2680)	104	3
87 (INT 7570)	109, 110	5
133	109	5
134	110	5
1017	105(T)	3
1024 (INT 7531)	107, 108(P)	4

International Charts	Notices	Pages
2610	102(T)	2
2680	104	3
7531	107, 108(P)	4
7570	109	5

SAN Publications	Notices	Pages
SA List of Lights and Radio Signals (SAN HO-1) - 2008 Edition	111	9
SA Sailing Directions Vol II (SAN HO-22) - 2002 Edition	112	9

SAN Charts - New Charts / Editions	Notices	Pages
Nil		

SAN Charts and Publications - Permanently Withdrawn	Notices	Pages
Nil		

SANHO Publications - New / New Editions	Notices	Pages
Nil		

I cont/...

Spheroid / GPS Positions

All positions quoted in these Notices are referred to the **Datum** indicated next to the chart number. On chart scales of **1: 100 000 and smaller**, positions from **GPS receivers** set to **WGS 84** may be plotted directly on these charts. Mariners are warned that **insertion of Clarke 1880 (or other) positions on Automatic Plotters which are set to WGS 84 Spheroid can result in inaccurate navigation practices.**

Temporary and Preliminary Notices

These are indicated by (T) or (P) after the notice number. These are printed on one side of the paper in order that they may be cut and filed and are placed at the end of Section II. To assist in filing, the year is indicated after the notice number. **Information from these notices is not included on charts before issue;** charts should be updated in pencil on receipt.

Permanent Notices

Permanent corrections in Section II are marked by a star adjacent to the notice number to indicate that the notice is based on original information. Periodic lists of permanent corrections pertaining to affected navigational charts and publications are published annually and copies may be obtained from the Hydrographic Office or through a Chart Agent.

Chart Corrections

Further details are contained in NP100 The Mariner's Handbook which should be consulted for the correct procedures of filing, inserting and noting all types of corrections on nautical charts and other hydrographic publications. The Handbook may be obtained from Admiralty Chart Agents in Cape Town and Durban. Consult SAN HO-6 for Symbols and Abbreviations used on SAN Charts and NP735 for an illustrated explanation of the IALA Maritime Buoyage System.

Provision of Notices to Mariners

These Notices are *gratis* and may be obtained on request from the Hydrographic Office or through the approved Chart Agents. Additional copies required of "block" chart corrections can also be obtained through the above procedure.

Radio Navigational Warnings

See Note at the start of Section VI.

GUIDANCE NOTES FOR VIEWING AND PRINTING NOTICES USING ADOBE ACROBAT

For optimum results when viewing and printing material from the PDF digital files please note the following:

The minimum specification is a 486 PC with Windows 3.1 and 4MB of RAM.

When printing data from the files, ensure the Fit to Page icon in the Adobe Acrobat print menu is switched off before printing. Otherwise large text pages will be compressed, or large size Blocks may not fit the chart.

If printing text or monochrome NM Blocks, the minimum specification is an Inkjet or good quality Laser Postscript printer with at least 6 MB of memory. (NB. If using a Postscript printer, ensure the Postscript printer driver is installed).

For printing Colour NM Blocks the minimum specification of printer is a good quality Ink Jet/Laser printer with 300 dpi resolution or greater.

If using certain types of Ink Jet printer ensure the setting is set to Dithered screening not Pattern screening.

Printed colour copies should be compared with the colour image on screen to ensure that all the colours have reproduced correctly. Printer property resolution and ink density may need to be increased or adjusted to obtain the best results.

Ensure the Colour Ink Cartridge is in accordance with the printer manufacturers specifications. Minimum paper specification for printing Colour NM Blocks is International paper size A4, thickness/weight 80 gsm paper. (The same paper as used for NM Blocks in the NM Weekly). NB. (Ensure the paper quality is in accordance with the Printer manufacturers specifications).

The Hydrographer does not accept any liability for the display and printing of these digital Notices to Mariners on the users equipment.

TEMPORARY NOTICES AND PRELIMINARY NOTICES
In force 28 November 2008

CANCELLED NOTICES

77(T)/06 Charts SAN 83 (INT 7530), 125, 126, 1024 (INT 7531)
69(T)/07 Charts SAN 125, 126, 1024 (INT 7531)
70(T)/07 Charts SAN 135, 1030 (INT 7561)
101(T)/07 Chart SAN 1003
40(T)/08 Chart SAN 1020 (INT 7521)
41(T)/08 Chart SAN 122

TEMPORARY NOTICES

2002 Series

89(T) Namibia Bogenfels Anchor Obstructions, Foul Area.

2003 Series

64(T) RSA Durban Oil Terminal SBM Buoy laid.

2005 Series

42(T) RSA Elandsbaai Scientific buoy deployed.

2006 Series

33(T) RSA Tugela Lighthouse Temporary light and structure.
40(T) RSA Mossel Bay Temporary buoys deployed.
65(T) RSA Richards Bay Harbour Pelican Island West Groyne North End light and East Groyne light unlit.
68(T) RSA Hondeklip Bay Temporary light and structure.
69(T) RSA Gordon's Bay Silting in harbour.
82(T) RSA Richards Bay LM2 front light unlit.
96(T) RSA Table Bay Submarine cable.
121(T) RSA East London Redeployment of Oceanographic Environmental Moorings.

2007 Series

27(T) Namibia Boat Bay Floating rope sighted.
28(T) Namibia Lüderitz M/V Sakawe Miner lost anchor with wire attached.
29(T) Namibia Lüderitz Floating ropes without markers.
30(T) Namibia Bogenfels Swamped mining tools and floating ropes.
31(T) RSA St Helena Bay R/V Africana deployed sub-sea buoy.
43(T) RSA Gordon's Bay Orange and blue mooring buoys.
96(T) Namibia Lüderitz Lost anchor.
99(T) Namibia Possession Island Anchor left.
100(T) Namibia Oranjemund Mooring wire rope left.
106(T) RSA Richards Bay Leading mark unlit.
107(T) Angola South Atlantic Ocean Restricted area established.
110(T) Namibia Possession Island Anchor left.
111(T) Namibia Oranjemund Anchor left.
118(T) RSA Mossel Bay Guard vessel.
126(T) Namibia Shearwater Bay Anchor lost.
128(T) Namibia Possession Island Anchor lost.

I cont/...

2008 Series

27(T)/08	Namibia	Walvis Bay	Research equipment deployed.
38(T)/08	Namibia	Possession Island	Lost anchor.
39(T)/08	Namibia	Baker's Bay	Foul ground.
85(T)/08	Namibia	Shearwater Bay	Anchor lost.
87(T)/08	RSA	Port of Cape Town	Buoys relocated.
102(T)/08	Namibia	Swakopmund	Unlit buoys deployed.
105(T)/08	RSA	Simon's Bay	Trials.

PRELIMINARY NOTICES

2007 Series

88(P)	RSA	Port of Durban	Dredging activities.
89(P)	RSA	Port of Durban	Construction Buoy.
90(P)	RSA	Port of Durban	Waverider Buoy.
91(P)	RSA	Port of Durban	Replacement of Buoy.
92(P)	RSA	Port of Richards Bay	New Channel Buoys.
108(P)	Angola	Kizomba C Oilfields	Developments.
130(P)	RSA	Port of Durban	Sector light.
131(P)	RSA	Port of Durban	Buoy placed.
132(P)	RSA	Port of Durban	Buoys placed.

2008 Series

108(P)	RSA	Port of Ngqura	Buoys placed.
--------	-----	----------------	---------------

II

ERRATUM

1. NTM 97/08 Page 3

October 2008 NOTICES TO MARINERS

Insert below legend: (R. Lt)

Example: ■ BLDG (80)
(R. Lt)

SA NAVY SAN CHARTS OF SOUTH AFRICA AND NAMIBIA THAT ARE REFERRED TO THE WGS 84 SPHEROID

27 (INT 204)	76 (INT 2640)	79 (INT 2670)	84 (INT 7540)
87 (INT 7570)	90 (INT 2051)	1001 (INT 2611)	1002 (INT 2631)
1012 (INT 2672)	1013 (INT 2681)	1020 (INT 7521)	1024 (INT 7531)
1025 (INT 7532)	1027 (INT 7541)	1030 (INT 7561)	1031 (INT 7562)
1032 (INT 7572)	1033 (INT 7571)	2004 (INT 9056)	
113	114	115	122
132	133	134	1003
1033	SC3	SC5	2051
			125
			1015
			126
			1016
			127
			1017

II cont/...

MISCELLANEOUS

1. Mariners are advised that the primary and most reliable means of communication with HYDROSAN for all messages is via Telex : 95 527946 (ANS BACK : NAVY SA) or alternatively via Facsimile number : +27 21 787 2228.
2. Current and archived South African Notices to Mariners are available in PDF format on the internet at Website: <http://www.sanho.co.za>

GENERAL: SA NAVY HYDROGRAPHIC OFFICE CONTACT DETAILS

1. Mariners and interested parties are advised to take note of the SA Navy Hydrographic Office contact details as amended. This will assist in future to prevent late action being taken on important navigational information due to this office being contacted over weekends, public holidays and after hours.
2. The relevant contact details can be found on the front page of the monthly Notices to Mariners, as well as the website at www.sanho.co.za.

CONVERTION TO 406 MHZ EMERGENCY DISTRESS BEACONS

1. Mariners and interestes parties are advised to take note that, due to world-wide technical upgrades, the old 121.5 MHz Emergency Distress Beacons will be phased out at the end of 2008. The 406 MHz Locator Beacons will be the only system that will be responded to until further notice. This beacon will be more reliable and more accurate in terms of beacon location.
2. The older 121.5 MHz system will be completely phased out and only the 406 MHz system signals will be processed by February 2009.

102(T) NAMIBIA, West Coast, Swakopmund - Buoys

Source: B-4 Eng & Diving CC (Previously issued as CNW 344 of 2008)

SAN 73 (INT 2610) - [Previous Update - 125/07] CLARKE 1880 DATUM



1. Unlit marker buoys centred in approximate position 22° 22'.62 S 014° 25'.39 E
2. Vessels, anglers and swimmers are requested to keep 1.5 nm clear of survey site.

(SAN 73)

103* NAMIBIA, West Coast, Oranjemund - Light, Oil pipeline

Source: Hydrographer

SAN 54 - [Previous Update - 98/05] CLARKE 1880 DATUM

1. Delete:  in approximate position 28° 35'.0 S 016° 22'.0 E
2. Insert:  between approximate positions
a. 29° 27'.5 S 011° 34'.8 E
b. 30° 47'.0 S 012° 59'.2 E

(SAN 54)

II cont/...

104* SOUTH AFRICA, South West Coast, Cape Point - Legend

Source: Hydrographer

SAN 56 - [Previous Update - 113/07] CLARKE 1880 DATUM

1. Insert: *(disused)* in approximate positions
- | | | |
|----|-------------|--------------|
| a. | 34° 38'.0 S | 018° 23'.0 E |
| b. | 35° 02'.0 S | 018° 00'.0 E |

SAN 80 (INT 2680) - [Previous Update - 80/08] CLARKE 1880 DATUM

1. Insert: *(disused)* in approximate position 35° 02'.0 S 018° 00'.0 E

(SAN 56, 80)

105(T) SOUTH AFRICA, South West Coast, Simon's Bay - Trials

Source: Hydrographer (Previously issued as CNW 524 of 2008)

SAN 1017 - [Previous Update - 72/08] WGS 84 DATUM

1. Underwater trials will be conducted over a period of approximately 12 months
- in the following approximate position 34° 10'.9 S 018° 26'.7 E
2. Underwater obstructions are marked by orange buoys. Vessels are requested to provide a 300 yard clear range with no transiting or anchoring.

(SAN 1017)

106* SOUTH AFRICA, South Coast - Note

Source: Hydrographer

SAN 57 - [Previous Update - 104/07] CLARKE 1880 DATUM

1. Substitute: Note in approximate position 33° 45'.0 S 022° 20'.0 E
- with new 'Note' in accompanying block correction.


(SAN 57)

II cont/...

107* SOUTH AFRICA, South Coast, Port of Ngqura - Buoy

Source: Hydrographer

SAN 1024 (INT 7531) - [Previous Update - 81/08] WGS 84 DATUM












1. Delete:		in approximate position	33° 49'.88 S	025° 41'.41 E
------------	---	-------------------------	--------------	---------------

(SAN 1024)

108(P) SOUTH AFRICA, South Coast, Port of Ngqura - Buoys

Source: TNPA

SAN 1024 (INT 7531) - [Previous Update - 107/08] WGS 84 DATUM

1. Insert:		in approximate position	33° 51'.73 S	025° 42'.50 E
2. Insert:		in approximate position	33° 50'.83 S	025° 41'.27 E
3. Insert:		in approximate position	33° 50'.12 S	025° 41'.17 E
4. Insert:		in approximate position	33° 49'.85 S	025° 41'.21 E
5. Insert:		in approximate position	33° 49'.59 S	025° 41'.26 E
6. Insert:		in approximate position	33° 49'.32 S	025° 41'.31 E
7. Insert:		in approximate position	33° 49'.05 S	025° 41'.36 E
8. Insert:		in approximate position	33° 50'.15 S	025° 41'.38 E
9. Insert:		in approximate position	33° 49'.88 S	025° 41'.41 E
10. Insert:		in approximate position	33° 49'.61 S	025° 41'.46 E
11. Insert:		in approximate position	33° 49'.35 S	025° 41'.51 E

(SAN 1024)

II cont/...

109* SOUTH AFRICA, East Coast, South of Cape Vidal - Wreck

Source: SAMSA (Previously issued as CNW 565 of 2008)

SAN 87 (INT 7570) - [Previous Update - 121/07] WGS 84 DATUM

1. Insert: +++ PA in approximate position 28° 09'.80 S 032° 34'.03 E

SAN 133 - [Previous Update - 52/07] WGS 84 DATUM

2. Insert: +++ PA in approximate position 28° 09'.80 S 032° 34'.03 E

3. The wreck is that of the barge Dar II, which was scuttled on 05 November 2008.

(SAN 87, 133)

110* SOUTH AFRICA, East Coast, East of Black Rock Point - Wreck

Source: SAMSA (Previously issued as CNW 552 of 2008)

SAN 87 (INT 7570) - [Previous Update - 109/08] WGS 84 DATUM

1. Insert: +++ PA in approximate position 27° 07'.90 S 032° 53'.60 E

SAN 134 - [Previous Update - 121/07] WGS 84 DATUM

2. Insert: +++ PA in approximate position 27° 07'.90 S 032° 53'.60 E

3. The wreck is that of the Russian trawler Diomed, which sank on 31 October 2008 during a failed towing operation.

(SAN 87, 134)

IIA

LIST OF TEMPORARY AND PRELIMINARY NOTICES TO MARINERS ISSUED BY THE ANGOLAN MINISTRY OF TRANSPORT IN FORCE

Important Notice : Mariners are advised that positions for Angolan Notices are referred to the WGS 84 Spheroid. Caution is therefore advised when plotting positions on large scale British Admiralty charts that are not based on the same spheroid.

Nil prior to these Notices.

2007 Series

NTM 107/07 (T)
NTM 108/07 (P)

South Atlantic Ocean - NE Sector
Kazomba C Oilfields

Restricted area established.
Developments.

2008 Series

Nil.

IIB

**LIST OF TEMPORARY AND PRELIMINARY NOTICES TO MARINERS ISSUED
BY THE MOZAMBIQUE INSTITUTE OF HYDROGRAPHY AND NAVIGATION
(INAHINA) IN FORCE**

Important Notice : Mariners are advised that positions for Mozambique Notices are referred to the WGS 84 Spheroid. Caution is therefore advised when plotting positions on large scale British Admiralty charts that are not based on the same spheroid.

Nil prior to these Notices.

2005 Series

MOZ 05/05 (T)	Port of Maputo	Cias de Bombagem temporarily unlit.
---------------	----------------	-------------------------------------

2006 Series

MOZ 11/06 (T)	Port of Inhambane	Buoy A out of position.
MOZ 12/06 (T)	Port of Inhambane	Buoy 9 out of position.

2007 Series

Nil.

2008 Series

MOZ 13/08(T)	Port of Maputo	Buoys and Lighthouses unlit.
MOZ 14/08(T)	Port of Maputo	Lighthouse unlit.
MOZ 17/08(T)	Port of Mocimboa da Praia	Buoy out of position.
MOZ 19/08(T)	Port of Beira	Buoy unlit.

**LIST OF TEMPORARY AND PRELIMINARY NOTICES TO MARINERS ISSUED
FOR MADAGASCAR IN FORCE**

Important Notice : Mariners are advised that positions for Madagascar Notices are referred to the WGS 84 Spheroid. Caution is therefore advised when plotting positions on large scale British Admiralty charts that are not based on the same spheroid.

Nil prior to these Notices.

2008 Series

Nil.

III

SAN HO CHARTS AND SAN HO PUBLICATIONS - NEW CHARTS/EDITIONS

Nil.

IV

CORRECTION TO SAN HO PUBLICATIONS

Nil.

ANNUAL SUMMARY OF SA NOTICES TO MARINERS 2008 EDITION

Nil.

V

111/08 CORRECTION TO SA LIST OF LIGHTS AND RADIO SIGNALS - SAN HO-1 2008 Edition

Page 54 RADIO SERVICES

COMMUNICATION SYSTEMS - Satellite - Para 3

1. Delete: 121.5 and
2. Delete: The 121.5 MHz service will be discontinued in 2005.

Page 57 RADIO SERVICES

MARITIME SEARCH AND RESCUE - Use of Aircraft in assisting Ships - Para 3

3. Delete: ,121.5 MHz

112/08 SOUTH AFRICAN SAILING DIRECTIONS VOL II (SAN HO-22) 4th EDITION - 2002

6.9 SEAL ISLAND TO CAPE HANGKLIP

1. Page 6-23 para 11

Insert after ... situated on the beachfront. A red **obstruction** light is exhibited on top of the building.

VI

NAVAREA VII and Coastal Navigational Warnings Bulletin in force as at 28 November 2008

See Annual NM 3/2007. Broadcast Warnings are available at Port Offices and remain valid until cancelled or until superseded by this and/or other broadcast bulletins.

NAVAREA VII MESSAGES

Nil Prior to these Messages

2008 Series

055	Indian Ocean - SW Sector - Port of Mahajunga	Survey operations.
072	Indian Ocean - SW Sector - Port of Mahajunga	Survey depths and wreck found.
102	Africa East Coast - Mozambique Channel	Buoys.
148	Africa East Coast - Mozambique Channel	Light unlit.
170	South Atlantic Ocean - NE Sector	Survey operations.
176	Riglist.	
180	Indian Ocean - SW Sector	Moorings deployed.
185	South Atlantic Ocean - NE Sector - Angola	Survey operations.
186	Messages in Force.	

COASTAL NAVWARNING MESSAGES

Nil Prior to these Messages

2008 Series

085	Namibia	Oranjemund	Coral Sea anchor spread.
176	Namibia	Chamais Bay	Namakwa anchor spread.
344	Namibia	Swakopmund	Buoys deployed.
370	RSA	Port Elizabeth	Buoy deployed.
378	RSA	Port of Nqgura	Buoys deployed.
409	RSA	Simon's Bay	Racing buoys.
418	RSA	Port of Durban	Buoy new position.
428	RSA	Cape Agulhas	FPSO Racon.
437	RSA	Port Elizabeth	Buoys out of position.
474	RSA	Port of Durban	Buoy new position.
475	RSA	Port of Durban	Buoy unlit.
478	RSA	Port of Cape Town	Light changes.
481	RSA	Richards Bay	Buoy dragging anchor.
492	RSA	Port of Mossel Bay	Light unlit.
497	RSA	Richards Bay	Buoy removed.
524	RSA	Simon's Bay	Underwater trials.
526	RSA	Richards Bay	Survey operations.
529	RSA	Cooper Light	DGPS.
530	RSA	SE Coast	Survey operations.
531	RSA	Durban	Buoy racon.
535	Namibia	Walvis Bay	Survey operations.
542	RSA	Durban	Buoy unlit and out of position.
552	RSA	Punta du Ouro	Vessel sank.
565	RSA	Leven Point	Barge scuttled.
577	Namibia	Lüderitz	D.F. Discoverer anchor spread.
579	RSA	Port Nolloth	Peace in Africa anchor spread.
580	RSA	Port Nolloth	Sampling operations.
586	Namibia	Lüderitz	Survey operations.
589	RSA	Port of Port Elizabeth	Fairway buoy unlit.

VI ANNEX A

USA Government Special Warning in force 18 December 2001

SPECIAL WARNING NUMBER 120 WORLDWIDE

1. Due to recent events in the Middle East and the American Homeland, U.S. Forces worldwide are operating at a heightened state of readiness and taking additional defensive precautions against terrorists and other potential threats. Consequently, all aircraft, surface vessels, and sub-surface vessels approaching U.S. Forces are requested to maintain radio contact with U.S. Forces on bridge-to-bridge channel 16, international air distress (121.5 Mhz VHF) or MILAIR distress (243.0 Mhz UHF).
2. U.S. Forces will exercise appropriate measures in self-defence if warranted by the circumstances. Aircraft, surface vessels, and sub-surface vessels approaching U.S. Forces will, by making prior contacts as described above, help make their intentions clear and avoid unnecessary initiation of such defensive measures.
3. U.S. Forces, especially when operating in confined waters, shall remain mindful of navigational considerations of aircraft, surface vessels, and sub-surface vessels in their immediate vicinity.
4. Nothing in the Special Warning is intended to impede or otherwise interfere with the freedom of navigation or overflight of any vessel or aircraft, or to limit or expand the inherent self-defence rights of U.S. Forces. This Special Warning is published solely to advise of the heightened state of readiness of U.S. Forces and to request that radio contact be maintained as described above. (Issued 16 Nov 2001).

USA Government Special Warning in force 20 March 2003

SPECIAL WARNING NUMBER 121 PERSIAN GULF

1. Coalition Naval Forces may conduct military operations in the Eastern Mediterranean Sea, Red Sea, Gulf of Aden, Arabian Sea, Gulf of Oman and Arabian Gulf. The timely and accurate identification of all vessels and aircraft in these areas are, critical to avoid the inadvertent use of force.
2. All vessels are advised that coalition Naval Forces are prepared to exercise appropriate measures in self-defense to ensure their safety in the event they are approached by vessels or aircraft. Coalition Forces are prepared to respond decisively to any hostile acts or indications of hostile intent. All maritime vessels or activities that are determined to be threats to Coalition Naval Forces will be subject to defensive measures, including boarding, seizure, disabling or destruction, without regard to registry or location. Consequently, surface vessels, sub-surface vessels and all aircraft approaching Coalition Naval Forces are advised to maintain radio contact on Bridge-to-Bridge channel 16, International Air Distress (121.5 MHZ VHF) or Military Air Distress (243.0 MHZ UHF).
3. Vessels operating in the Middle East, Eastern Mediterranean Sea, Red Sea, Gulf of Oman, Arabian Sea and Arabian Gulf are subject to query, being stopped, boarded and searched by US/Coalition warships operating in support of operations against Iraq. Vessels found to be carrying contraband bound for Iraq or carrying and/or laying Naval mines are subject to detention, seizure and destruction. This notice is effective immediately and will remain in effect until further notice.

VI
ANNEX A/cont...

USA Government Special Warning in force 11 March 2005

SPECIAL WARNING NUMBER 122 EAST AFRICA

1. The US Government has received unconfirmed information that terrorists may attempt to mount a maritime attack using speed-boats against a western ship - possibly in East Africa. No additional information is available on the planning, timing or intended targets of the maritime attack. This notice is effective immediately and will remain in effect until further notice.

USA Government Special Warning in force 11 November 2005

SPECIAL WARNING NUMBER 123 EAST AFRICA

1. Due to continuing conditions of armed conflict and lawlessness in Somalia and waters off its coast, mariners are advised to avoid the port of Muqdisho (Mogadishu) and to remain at least 200 nautical miles distant from the Somali coast. The US government does not have an embassy in Somalia and cannot provide services to US citizens.
2. Recent vessel hijackings off the east coast of Somalia demonstrate that pirates are able to conduct at sea hijackings from as far south as Kismaayo (Chisimayu) (00-22S), though vessels are advised to transit no closer than 02-00S, to as far north as Eyl (08-00N), and out to a distance of 170 miles. The first known attempt to hijack a cruise vessel occurred in November 2005. All merchant vessels transiting the coast of Somalia, no matter how far offshore, should increase anti-piracy precautions and maintain a heightened state of vigilance. Pirates are reported to have used previously hijacked ships as bases for further attacks.
3. Another reported pirate tactic has been to issue a false distress call to lure a ship close inshore. Therefore, caution should be taken when responding to distress calls keeping in mind it may be a tactic to lure a vessel into a trap.
4. Victimized vessels have reported two to three (2-3) speedboats measuring six to nine meters (6-9M) in length. Each vessel has a crew of three to six (3-6) armed men with AK-47s and shoulder launched rockets, which are opening fire on vessels in broad daylight in order to intimidate them into stopping.
5. To date, vessels that increase speed and take evasive maneuvers avoid boarding while those that slow down are boarded, taken to the Somali coastline, and released after successful ransom payment, often after protracted negotiations of as much as 11 weeks.

HYDROGRAPHIC NOTE

(for instructions, see overleaf)

Date

Ref. No

Name of ship or sender :

Address of sender :

.....

.....

Tel/Fax/Telex No. e-mail address of sender (if appropriate) :

General locality Subject :

Position : Lat : Long :

SAN Chart(s) affected : Edition dated :

Position fixing system used : Datum set :

Latest Monthly Edition of Notice to Mariners held :

Publications affected : (Edition No date of latest supplement, page and Light List No. etc.)

Details:

A replacement copy of Chart(s) No(s) is required, but see 4 overleaf.

Signature of observer/reporter :

HYDROGRAPHIC NOTE

Forwarding Information for South African Charts and Hydrographic Publications

INSTRUCTIONS

1. Mariners are requested to notify the Hydrographer of the South African Navy, Private Bag X1, Tokai, 7966, or by Facimile 021 7872228 or E-mail *hydrosan@iafrica.com* when new or suspected dangers to navigation are discovered, changes observed in aids to navigation, or corrections to publications seen to be necessary. The *Mariner's Handbook (NP 100) Chapter 8* gives general instructions. The provisions of international and national laws should be complied with when forwarding such reports.

2. This form and its instructions have been designed to help both the sender and the recipient. It should be used, or followed closely, whenever appropriate. Copies of this Form may be obtained gratis from the SAN Hydrographic Office at the above address or principal Chart Agents (see *Annual Notice to Mariners No. 1*).

3. When a **position** is defined by sextant angles or bearings (true or magnetic being specified) more than two should be used in order to provide a check. Distances observed by radar and the readings of Loran, Decca, etc., should be quoted. Latitude and longitude should only be used specifically to position the details when they have been fixed by astronomical observations or GPS and a full description of the method, equipment and datum (where applicable) used should be given.

4. A cutting from the largest scale chart is the best medium for forwarding details, the alterations and additions being shown thereon in red. When requested, a new copy will be sent in replacement of a chart that has been used to forward information, or when extensive observations have involved defacement of the observer's chart. If it is preferred to show the amendments on a tracing of the largest scale chart (rather than on the chart itself) these should be in red as above, but adequate details from the chart must be traced in black ink to enable the amendments to be fitted correctly.

5. When **soundings** are obtained *The Mariner's Handbook (NP 100)* should be consulted. The echo sounding trace should be marked with times, depths, etc., and forwarded with the report. It is important to state whether the echo sounder is set to register depths below the surface or below the keel; in the latter case the vessel's draught should be given. Time and date should be given in order that corrections for the height of the tide may be made where necessary. The make, name and type of set should also be given.

6. Modern **echo sounders** frequently record signals from echoes received back after one or more rotations of the stylus have been completed. Thus with a set whose maximum range is 500m, an echo recorded at 50m may be from depths of 50m, 550m or even 1050m. Soundings recorded beyond the set's nominal range can usually be recognised by the following:

- (a) the trace being weaker than normal for the depth recorded,
- (b) the trace passing through the transmission line,
- (c) the feathery nature of the trace.

As a check that apparently shoal soundings are not due to echoes received beyond the set's nominal range, soundings should be continued until reasonable agreement with charted soundings is reached. However, soundings received after one or more rotations of the stylus can still be useful and should be submitted if they show significant differences from charted depths.

7. Reports which cannot be confirmed or are lacking in certain details should not be withheld. Shortcomings should be stressed and any firm expectation of being able to check the information on a succeeding voyage should be mentioned.

8. Reports of **shoal soundings**, uncharted dangers and navigational aids out of order should, at the mariner's discretion, also be made by radio to the nearest coast radio station. The draught of modern tankers is such that any uncharted depth under 30 metres or 15 fathoms may be of sufficient importance to justify a radio message.

9. **Port information** should be forwarded on Form HO-16a together with Form HO-16. Form HO-16a lists the information required for South African Sailing Directions and should be used as an *aide memoire*. Where there is insufficient space on the form an additional sheet should be used.

Note : An acknowledgement or receipt will be sent and the information then used to the best advantage which may mean immediate action or inclusion in a revision in due course. When a Notice to Mariners is issued, the sender's ship or name is quoted as authority unless (as sometimes happens) the information is also received from other authorities. An explanation of the use made of contributions from all parts of the world would be too great a task and a further communication should only be expected when the information is of outstanding value or has unusual features.

HO-16a (March 2004)

**HYDROGRAPHIC NOTE FOR PORT
INFORMATION**

(To accompany Form HO-16)

Name of ship or sender :

Address of sender :

Ref. No.

.....

Date :

.....

1. NAME OF PORT	
2. GENERAL REMARKS Principal activities and trade. Latest population figures and date. Number of ships or tonnage handled per year. Maximum size of vessel handled. Copy of Port Handbook if available.	
3. ANCHORAGES Designation, depths, holding ground, shelter afforded.	
4. PILOTAGE Authority for requests. Embarkation position. Regulations.	
5. DIRECTIONS Entry and berthing information. Tidal Streams. Navigational aids.	
6. TUGS Number available and max. hp.	
7. WHARVES Names, numbers or positions. Lengths. Depths alongside. Heights above Chart Datum. Facilities available.	
8. CARGO HOLDING Containers, lighters, Ro-Ro etc.	
9. CRANES Brief details and max. capacity.	

<p>10. REPAIRS</p> <p>Hull, machinery and underwater. Ship and boat yards. Docking or slipping facilities. Give size of vessels handled or dimensions. Hards or ramps. Divers.</p>	
<p>11. RESCUE AND DISTRESS</p> <p>Salvage, lifeboat, NSRI, etc.</p>	
<p>12. SUPPLIES</p> <p>Fuel with type and quantities available. Fresh water with rate of supply. Provisions.</p>	
<p>13. SERVICES</p> <p>Medical. De-ratting. Consuls. Ship chandlery, compass adjustment, tank cleaning, hull painting.</p>	
<p>14. COMMUNICATIONS</p> <p>Road, rail and air services available. Nearest airport or airfield. Port radio and information service with frequencies and hours of operating.</p>	
<p>15. PORT AUTHORITY</p> <p>Designation, address and telephone number.</p>	
<p>16. SMALL CRAFT FACILITIES</p> <p>Information and facilities for small craft (eg yachts) visiting the port. Yacht Clubs, berths, etc.</p>	
<p>17. VIEWS</p> <p>Photographs (where permitted) of the approaches, leading marks, the entrance to the harbour etc. Picture postcards may also be useful.</p>	

Signature of observer/reporter

NAVIGATIONAL AIDS, WRECKS AND OBSTRUCTIONS

Certain lights, navigational aids, wrecks and obstructions have been omitted from this chart. For further details of these, the larger scale charts and relevant hydrographic publications should be consulted.

NAVIGATIONAL AIDS, WRECKS AND OBSTRUCTIONS

Certain lights, navigational aids, wrecks and obstructions have been omitted from this chart. For further details of these, the larger scale charts and relevant hydrographic publications should be consulted.