


I

2/2000

1.

*32

**SOUTH AFRICA, West Coast - Saldanha Bay - Mussel Culture Area Established
- Buoys - Light.**

1. Insert : Mussel Culture pecked line limits encompassing ;
Mole a. 33°01'28".2 S., 017°57'51".7 E.
b. 33°01'27".4 S., 017°57'53".8 E.
Buoy S4 c. 33°01'15".1 S., 017°57'43".5 E.
Light Fl.2s d. 33°01'24".0 S., 017°57'35".0 E.
(Positions WGS 84)
 2. Delete :  in approximate position; 33°00'.61 S., 017°59'.35 E.
 3. Renumber: Buoy A5 to read A7
in approximate position ; 150 metres ESE of 2 above.
 4. Amend : Light on breakwater end to read Fl.2s in approximate position ;
33°01'.39 S., 017°57'.64 E.
 5. Insert : Mussel Culture pecked line limits encompassing ;
Mole a. 33°01'.45 S., 017°57'.91 E.
b. 33°01'.44 S., 017°57'.94 E.
Buoy S4 c. 33°01'.23 S., 017°57'.79 E.
Light Fl.2s d. 33°01'.39 S., 017°57'.64 E.
 6. Insert : Legend *Mussel Culture Area* (see Note).
in approximate position; 33°01'.38 S., 017°57'.74 E.
(WGS 84 and Clarke 1880)
- SAN Charts : 1012(INT 2672) (1, 2, 3, 6) (NE)
1011 (4, 5, 6) (77/99)
SC 2 (Saldanha Bay and Lagoon) (5, 6)
SC 2 (Saldanha Bay. Small Craft Area Plan) (5, 6) (86/98)
- Source : Port Engineer, Saldanha Bay Harbour. (SAN 1011,1012, SC 2)

I

2/2000

2.


***33**

SOUTH AFRICA, South Coast - Port Elizabeth Approaches - Entry Prohibited Areas Discontinued.

1. Delete : *Entry Prohibited Areas* (legend and limits)
centered on positions
- a. 33°56'.55 S., 025°37'.70 E.
 - b. 33°57'.01 S., 025°37'.90 E
 - c. 33°57'.03 S., 025°37'.90 E
- SAN Charts : 1024 (1a,b) (41/99)
1025 (Port Elizabeth Plan) (1a,b) (41/99)
SC 9 (Port Elizabeth Plan) (1c) (NE)
- Source : SAS DONKIN (Hydrographic Note) (SAN 1024, 1025, SC 9)

***34**

SOUTH AFRICA, East Coast - Margate - Aero RC Discontinued.

- Delete :  Aero RC in approximate pos'n 30°51' S., 030°21' E.
- SAN Charts : 130 (23/00)
131 (45/99)
- Source : Dept. of Transport (Civil Aviation). (SAN 130, 131)

IA

2/2000

3.

LIST OF TEMPORARY AND PRELIMINARY NOTICES TO MARINERS ISSUED BY THE MOZAMBIQUE INSTITUTE OF HYDROGRAPHY AND NAVIGATION (INAHINA) IN 2000

1998 Series

2MOZ(T)	Port of Beira -	Lit Waverider buoy laid.
3MOZ(P)	Port of Beira -	White Spar buoy laid.
4MOZ(T)	Port of Maputo -	No. 4 Buoy temp. unlit.

1999 Series

2MOZ(P)/99	Port of Maputo -	No. 2S Buoy characteristic changed.
3MOZ(T)/99	Port of Mocimboa da Praia -	No. 9, 13, 14 Buoys withdrawn.
8MOZ(T)/99	Port of Beira -	New Buoyage.
12MOZ(P)/99	Port of Quelimane -	Depths.
13MOZ(T)/99	Port of Inhambane -	Ponta Zavora (D6528) temp. unlit.
17MOZ/99	Port of Mocimboa da Praia -	Lipulula Light (D6645) unlit.
18MOZ/99	Port of Mocimboa da Praia -	Comangano Light (D6646) unlit.
19MOZ/99	Port of Mocimboa da Praia -	Rovura Light (D6644) unlit.
21MOZ(T)/99	Port of Maputo -	Racon on Buoy No. 1N. temp. withdrawn.

2000 Series

Nil received in January & February.

IV

2/2000

4.

35

CORRECTIONS TO LIST OF LIGHTS - SAN HO-1 (NEW EDITION 2000).

1. pg 22. DURBAN HARBOUR *Zp 6248 Fairway Buoy.*
Amend : **Racon (Q)** (Col 8)
2. pg 34. AERO RADIO BEACON LISTING. SOUTH AFRICA.
Delete : 1851 **MGT Margate** (in toto).
3. pg 36. 7396.1 Durban Harbour (Fairway Buoy).
Amend : **Racon Q** (Col 2)
4. pg 37. LOCATION OF RADIO BEACONS AND RACONS
Delete : 1851 adjacent to *Margate*
5. pg 45. PORT METEOROLOGICAL SERVICES
Amend : Cape Town Telephone Number to read (021) 934 0450.
6. pg 46. WEATHER BROADCAST SCHEDULES, Cape Town Radio.
Delete : Frequencies 18306 and 22540 (Col 3)
(Note; ITU Channel Numbers will now tie in with remaining frequencies)
7. pg 54. Cape Naval (ZSJ)
Delete : Note 4. Bracketed text; (date of commencement ..to... announced).
8. pg 55. 1. AFMET WEATHER.
Amend : Hours of Transmission.
4014 1600 - 0600
18238 0600 - 1600
9. pg 56. DURBAN. 3. RADIO TELEPHONY ON VHF SERVICE.
Amend : Durban ITU Working Ch. to read **26** and **01**.
Richards Bay ITU Working Ch. to read **28** and **24**.

IV

2/2000
5.

35 (CONTINUED)

10. pg 57. 5. AUTOLINK.
Amend : Durban ITU Working Ch. to read **01.**
Richards Bay ITU Working Ch. to read **24.**
11. pg 59. RADIO TELEPHONE VHF STATIONS.
Amend : a. Richards Bay Block TRFC TWO to read 24.
b. Durban Block TRFC TWO to read 01.
12. pg 60. AUTOLINK RT.
Amend : a. Richards Bay Block to read 24.
b. Durban Block to read 01.
13. pg 47. Substitute : Existing text (in toto) with block on page 6.