





## IA

5/00

3.

### LIST OF TEMPORARY AND PRELIMINARY NOTICES TO MARINERS ISSUED BY THE MOZAMBIQUE INSTITUTE OF HYDROGRAPHY AND NAVIGATION (INAHINA) in 2000

#### 1998 Series

2MOZ(T)	Port of Beira -	Lit Waverider buoy laid.
3MOZ(P)	Port of Beira -	White Spar buoy laid.
4MOZ(T)	Port of Maputo -	No. 4 Buoy temp. unlit.

#### 1999 Series

02MOZ(P)/99	Port of Maputo -	No. 2S Buoy characteristic changed.
03MOZ(T)/99	Port of Mocimboa da Praia -	No. 9, 13, 14 Buoys withdrawn.
08MOZ(T)/99	Port of Beira -	New Buoyage.
12MOZ(P)/99	Port of Quelimane -	Depths.
13MOZ(T)/99	Port of Inhambane -	Ponta Zavora (D6528) temp. unlit.
21MOZ(T)/99	Port of Maputo -	Racon on Buoy No. 1N. temp. withdrawn.

#### 2000 Series

02MOZ(T)/00	Port of Pemba (Amelia) -	Romero Light (D6630) temp. unlit.
-------------	--------------------------	-----------------------------------

**Nil in May.**

## IV

5/00  
4.

62

### CORRECTIONS TO LIST OF LIGHTS - SAN HO 1 (NEW EDITION 2000).

1. p.19.  
Insert : *Z6031 (D6377.1)* (col 1)  
***E.M.Control Buoy*** (col 2)  
34 54.8  
21 47.6 (col 3)  
*Mo(X)Y*  
**Horn Mo(U)** (col 4)  
27 (col 5)  
10 (col 6)  
Yellow Lattice Structure (27) (col 7)  
**Racon (X)** (col 8)
  
2. p. 21. **PORT ALFRED**  
Z6160 South Breakwater  
Insert : **(Root)** (col 2)  
Substitute : 5 (col 6)  
Delete : 5 (col 7)  
Insert : Square Lattice tower (4) (col 7)